

Electrical Installation Condition Report

for Domestic and Similar Premises up to 100 A

Requirements for Electrical Installations BS 7671:2018 (IET Wiring Regulations 18th Edition) NA/ 1 2 9 0 9 0 0 0 0 1 1 4 4 EICR Page 2 of 6

Details of till	e Installation			
Client	mr z iqbal	Ins	tallation	
Address	Zafs 33 Heslington Road YORK	Ad	dress	2 Alne Terrace YORK
Postcode	YO10 5AR	Po	estcode	YO10 5AW
Reason for plandlords safety ce	producing this report This form	n is to be used only	for reporting on the	condition of an existing installation.
Date(s) on which the	ne inspection and testing were carried out 2	29/04/2022	to 29/04/2022	
Details of in	stallation which is the subject	ct of this report		
Description of pren				
Estimated age of th		vears	Other (please s	specify)
Evidence of alterat		Not apparent	if 'Vac' actimate	4 40
Records of installar			if 'Yes', estimate	d 10 years years
		Records held b	AND SHEET AND ASSESSMENT OF THE PARTY OF THE	
Date of last inspec	tion Not Known Electri	ical Installation Certific	ate No. or previous Insp	ection Report No.
Extent of electrics	al installation covered by this report:	PERSONAL PROPERTY.	Agrood I Imitations a	
			no I/n insulation test	and Operational Limitations (Regulations 653.2)
visual and electrica	al test, 10% checks at points			
	al test, 10% checks at points			
	al test, 10% checks at points		4	
	al test, 10% checks at points			
visual and electrica	al test, 10% checks at points		Agreed with: nwner	
visual and electrical Operational limitation	ions including the reasons see page no 1	npanving schedule has	Agreed with: owner	
Visual and electrical Operational limitati The inspection and	ions including the reasons see page no 1 I testing detailed within this report and according	mpanying schedule has	been carried out in acc	ordance with BS 7671: 2018 amended to 2020
Operational limitati The inspection and It should be noted been inspected uni	ions including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client ar	onduite under floore in	s been carried out in acc	
Operational limitati The inspection and	ions including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client ar	onduite under floore in	s been carried out in acc	ordance with BS 7671: 2018 amended to 2020 rally within the fabric of the building or underground have ron should be made within an accessible roof space housing
Operational limitati The inspection and It should be noted been inspected un other electrical equ	tions including the reasons see page no 1 It testing detailed within this report and accontinated that cables concealed within trunkings and cless specifically agreed between the client artipment.	conduits, under floors, in and inspector prior to the	s been carried out in acc	
Operational limitati The inspection and It should be noted been inspected un other electrical equ Summary of General conditions	ions including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client ar	conduits, under floors, in and inspector prior to the	s been carried out in acc	
Operational limitati The inspection and It should be noted been inspected uniother electrical equi	tions including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client aritipment. The condition of the installat	conduits, under floors, in and inspector prior to the	s been carried out in acc	
Operational limitati The inspection and It should be noted been inspected uniother electrical equ Summary of General conditions good	tions including the reasons see page no 1 I testing detailed within this report and acconditated that cables concealed within trunkings and cless specifically agreed between the client aritipment. Ithe condition of the Installation of the installation (in terms of safety)	conduits, under floors, indinspector prior to the	s been carried out in acc	
Operational limitati The inspection and It should be noted been inspected un other electrical equ Summary of General conditions good Overall assessment	tons including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client arithment. Ithe condition of the installation (in terms of safety)	conduits, under floors, indinspector prior to the	s been carried out in acc n roof spaces and gener e inspection. An inspecti	rally within the fabric of the building or underground have r on should be made within an accessible roof space housing the space housing
Operational limitati The inspection and It should be noted been inspected un other electrical equ Summary of General conditions good Overall assessment	tons including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client arithment. Ithe condition of the installation (in terms of safety)	conduits, under floors, indinspector prior to the	s been carried out in acc n roof spaces and gener e inspection. An inspecti	rally within the fabric of the building or underground have r on should be made within an accessible roof space housi
Operational limitati The inspection and It should be noted been inspected uniother electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT	tons including the reasons see page no 1 I testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client aritipment. I the condition of the installation (in terms of safety) Int of the installation in terms of its suitability of the installati	conduits, under floors, indinspector prior to the	s been carried out in acc n roof spaces and gener e inspection. An inspecti	rally within the fabric of the building or underground have r on should be made within an accessible roof space housing the space housing
Operational limitation The inspection and it should be noted been inspected uniother electrical equipment of General conditions good Overall assessment An UNSATISFACT	It to the installation in terms of its suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installations	conduits, under floors, indinspector prior to the close t	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu	rally within the fabric of the building or underground have ron should be made within an accessible roof space housing should be made within an accessible roof space housing should be made within an accessible roof space housing should be made within an accessible roof space housing should be sh
Operational limitati The inspection and It should be noted been inspected uniother electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT Recommence Where the overall classified as 'Dan'	tons including the reasons see page no 1 I testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client aritipment. The condition of the installation of the installation of the installation (in terms of safety) Int of the installation in terms of its suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installation of the installation of the suitability of the installations.	conduits, under floors, indinspector prior to the clion for continued use code C1), or potentially action for continued use rous' (code C2) are as rous' (code C2) are as	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fi	rally within the fabric of the building or underground have ron should be made within an accessible roof space housing space housing the space housing space housing space. SATISFACTORY *UNSATISFACTORY unther investigation (code FI) conditions have been identified the space of the space o
Operational limitati The inspection and It should be noted been inspected uniother electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT Recommence Where the overall classified as 'Dan'	tons including the reasons see page no 1 I testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client aritipment. The condition of the installation of the installation of the installation (in terms of safety) Int of the installation in terms of its suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installation of the installation of the suitability of the installations.	conduits, under floors, indinspector prior to the clion for continued use code C1), or potentially action for continued use rous' (code C2) are as rous' (code C2) are as	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fi	rally within the fabric of the building or underground have ron should be made within an accessible roof space housing the space housing space. SATISFACTORY *UNSATISFACTORY urther investigation (code FI) conditions have been identified.
Operational limitation The inspection and It should be noted been inspected unito other electrical equipment of General conditions good Overall assessment An UNSATISFACT Recomment Where the overall classified as 'Dan observations iden	tons including the reasons see page no 1 I testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client aritiment. The condition of the installation of the installation of the installation (in terms of safety) In of the installation in terms of its suitability of the installations assessment of the suitability of the installation of the suitability of the suitability of the installation of the suitability of	for continued use code C1), or potentially ation for continued use code C2), or potentially code C2) are adde F1). Observations	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu s above is stated as UN cted upon as a matter oc classified as 'Improvem	rally within the fabric of the building or underground have ron should be made within an accessible roof space housing space housing the space housing space housing space. SATISFACTORY IV. SA
Operational limitati The inspection and It should be noted been inspected uniother electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT Recommenc Where the overall classified as 'Dan observations iden consideration. Sui	tons including the reasons see page no 1 I testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client aritipment. The condition of the installation of the installation of the installation (in terms of safety) Int of the installation in terms of its suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installation of the installation of the suitability of the installations.	for continued use code C1), or potentially ation for continued use code C2), or potentially code C2) are adde F1). Observations	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu s above is stated as UN cted upon as a matter oc classified as 'Improvem	rally within the fabric of the building or underground have roon should be made within an accessible roof space housing satisfactory with the fabric of space housing satisfactory with the fabric of
Operational limitati The inspection and It should be noted unbeen inspected unbeen inspection and General conditions good Overall assessmer "An UNSATISFACT Recommence Where the overall classified as "Dan observations iden consideration. Sul	It testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client ariginment. It the condition of the installation of the installation of the installation (in terms of safety) In the of the installation in terms of its suitability of the installations assessment indicates that dangerous (or code C1) or 'Potential danger greyersent' (code C1) or 'Potential danger tiffied as 'Further Investigation required' (codect to the necessary remedial action being the second code to the necessary remedial action being the second code to the necessary remedial action being the second code to the necessary remedial action being the second code to the necessary remedial action being the second code to the necessary remedial action being the second code to the necessary remedial action being the second code to the necessary remedial action being the second code to the second	for continued use code C1), or potentially atton for continued use code C1), or potentially atton for continued use rous' (code C2) are a rode FI). Observations og taken, I/we recomm	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fo s above is stated as UN cted upon as a matter of classified as 'Improvemend that the installation	sally within the fabric of the building or underground have reported by the made within an accessible roof space housing should be made within an accessible roof space housing the made within an accessible roof space housing sall should be made within an accessible roof space housing sall should be made within an accessible roof space housing sall should be seen identified sall should be seen identified sall should be given due to should be given due it is further inspected and tested by 29/04/2027 (dietal should be given due)
Operational limitati The inspection and It should be noted been inspected uniother electrical equiother and considerations and observations identical electrical ele	testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client aritiment. The condition of the installation of the installation of the installation (in terms of safety) In of the installation in terms of its suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installation of the installation of the installations assessment of the suitability of the installation of the installation of the suitability of the installation of the suitability of the installation of the suitability of the installation of the instal	for continued use code C1), or potentially ation for continued use rous' (code C2) are and eFi). Observations ag taken, I/we recomm testing of the electricathen carrying out the interesting the electricathen carrying the	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu e above is stated as UN cted upon as a matter oclassified as "Improvement that the installation l installation (as indicate	satisfactory "Unsatisfactory "Unsatisf
Operational limitati The inspection and It should be noted under electrical equ Summary of General conditions good Overall assessmer "An UNSATISFAC" Recommence Where the overall classified as "Dan observations iden consideration. Sul Declaration I/we being the pers described above, to observations and to	It testing detailed within this report and acconditated cables concealed within trunkings and cless specifically agreed between the client ariginant. It the condition of the installation of the installation of the installation (in terms of safety) In the condition of the installation	for continued use code C1), or potentially ation for continued use rous' (code C2) are and eFi). Observations ag taken, I/we recomm testing of the electricathen carrying out the interesting the electricathen carrying the	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu e above is stated as UN cted upon as a matter oclassified as "Improvement that the installation l installation (as indicate	sally within the fabric of the building or underground have reported by the made within an accessible roof space housing should be made within an accessible roof space housing the made within an accessible roof space housing sall should be made within an accessible roof space housing sall should be made within an accessible roof space housing sall should be seen identified sall should be seen identified sall should be given due to should be given due it is further inspected and tested by 29/04/2027 (dietal should be given due)
Operational limitati The inspection and It should be noted been inspected un other electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT Recommence Where the overall classified as 'Dan observations iden consideration. Sui Declaration I/we being the persence of the consideration and it in section D of this	testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client aritipment. The condition of the installation (in terms of safety) Int of the installation (in terms of its suitability of the installation (in terms of safety) TORY assessment indicates that dangerous (of the installation of the suitability of the installations) assessment of the suitability of the installation assessment of the suitability of the installation of the suitability of the installations. Tory assessment (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code	for continued use code C1), or potentially ation for continued use rous' (code C2) are and eFi). Observations ag taken, I/we recomm testing of the electricathen carrying out the interesting the electricathen carrying the	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu e above is stated as UN cted upon as a matter or classified as 'Improvem end that the installation I installation (as indicate spection and testing he indition of the electrical i	satisfactory "Unsatisfactory "Unsatisf
Operational limitati The inspection and It should be noted useen inspected and other electrical equ Summary of General conditions good Overall assessmer "An UNSATISFAC" Where the overall classified as "Dan observations iden consideration. Sul Declaration I/we being the pers described above, tobservations and to in section D of this Company	testing detailed within this report and acconditated cables concealed within trunkings and cless specifically agreed between the client an injument. The condition of the installation of the installation of the installation (in terms of safety) In the condition of the installation of the installation of the installation (in terms of its suitability of the installations assessment indicates that dangerous (conditions) In the installation of the suitability of the installations assessment of the suitability of the installations.	for continued use code C1), or potentially ation for continued use code C2) are a de Fi). Observations ag taken, I/we recomm testing of the electrical then carrying out the ir e assessment of the co	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu s above is stated as UN cted upon as a matter or classified as 'Improvem end that the installation I installation (as indicate respection and testing he indition of the electrical i	SATISFACTORY *UNSATISFACTORY urther investigation (code Fi) conditions have been identified SATISFACTORY I/we recommend that any observation of urgency. Investigation without delay is recommended the performance of the
Operational limitati The inspection and It should be noted been inspected un other electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT Recommence Where the overall classified as 'Dan observations iden consideration. Sui Declaration I/we being the persence of the second of this section D of this in section D of this	testing detailed within this report and acconditate cables concealed within trunkings and cless specifically agreed between the client aritipment. The condition of the installation (in terms of safety) Int of the installation (in terms of its suitability of the installation (in terms of safety) TORY assessment indicates that dangerous (of the installation of the suitability of the installations) assessment of the suitability of the installation assessment of the suitability of the installation of the suitability of the installations. Tory assessment (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code C1) or 'Potential danger tified as 'Further Investigation required' (code	for continued use code C1), or potentially ation for continued use rous' (code C2) are and eFi). Observations ag taken, I/we recomm testing of the electricathen carrying out the interesting the electricathen carrying the	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu e above is stated as UN cted upon as a matter or classified as 'Improvem end that the installation I installation (as indicate spection and testing he ndition of the electrical i Inspected and nik stokes	SATISFACTORY *UNSATISFACTORY **UNSATISFACTORY **UNSATISF
Operational limitati The inspection and It should be noted under the sheen inspected and the relectrical equality of General conditions good Overall assessmer *An UNSATISFACT Recommence Where the overall classified as 'Dan observations iden consideration. Sul	testing detailed within this report and acconditated cables concealed within trunkings and cless specifically agreed between the client an injument. The condition of the installation of the installation of the installation (in terms of safety) In the condition of the installation of the installation of the installation (in terms of its suitability of the installations assessment indicates that dangerous (conditions) In the installation of the suitability of the installations assessment of the suitability of the installations.	for continued use code C1), or potentially ation for continued use code C2) are a de Fi). Observations ag taken, I/we recomm testing of the electrical then carrying out the ir e assessment of the co	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu s above is stated as UN cted upon as a matter or classified as 'Improvem end that the installation I installation (as indicate respection and testing he indition of the electrical i	SATISFACTORY *UNSATISFACTORY urther investigation (code Fi) conditions have been identified SATISFACTORY I/we recommend that any observation of urgency. Investigation without delay is recommended the performance of the
Operational limitati The inspection and It should be noted been inspected uni other electrical equ Summary of General conditions good Overall assessmer *An UNSATISFACT Recommence Where the overall classified as 'Dan observations iden consideration. Sul Declaration I/we being the per described above, to observations and to observation D of this Company Membership No.	testing detailed within this report and acconthat cables concealed within trunkings and cless specifically agreed between the client arigiment. the condition of the installation of the installation of the installation (in terms of safety) at of the installation in terms of its suitability for the installations assessment indicates that dangerous (color separate in the installation of the suitability of the installations assessment of the suitability of the installations assessment of the suitability of the installation as 'Further Investigation required' (color included as 'Further Investigation required' (color included as 'Further Investigation sequired' (color included as 'Further	for continued use code C1), or potentially ation for continued use code C1), or potentially ation for continued use rous' (code C2) are and eFi). Observations ag taken, I/we recomm testing of the electrical free carrying out the ire assessment of the converse.	been carried out in acc n roof spaces and gener e inspection. An inspecti dangerous (code C2), Fu e above is stated as UN cted upon as a matter or classified as 'Improvem end that the installation I installation (as indicate spection and testing he ndition of the electrical i Inspected and nik stokes	SATISFACTORY *UNSATISFACTORY **UNSATISFACTORY **UNSATISF

H Schedule(s)

schedule(s) of inspection and 1 schedule(s) of test results are attached,

The attached schedule(s) are part of this document and this report is valid only when they are attached to it.