

Landlord Gas Safety Record

Cert. No. 9854

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landlord						
Company Address		Nicky Cass Nortons Heating				Address	ss 36					Company	Mr Pau	Mr Paul Blades						
						Address						Address	4	4						
		Suite 4a Heritage House						Second Avenue						Hill Garth, Elvington						
		Osbaldwick					Y	York							York					
		York				Post Code		YO31 0RX						TOIK	TOTK					
		YO19 5UW				Tel. No						Post Code	YO41 5	YO41 5BP						
Tel No.					Tel. NO		Unknown				Tel. No	10111	1041 381							
Gas Safe Reg		01904 411040																		
ID Card No.																				
ID Card No.		5329584																		
Appliar	nce De	etails				1		Inspec	tion Details				'							
Location				Make	Mod	el	Flue Type	pe Landlord's Appliance Inspected			Heat Input (kW/h)	High Combu	stion Low Combu	stion Safety d	evice(s) Ventilation	Visual condition		Appliance	Appliance safe	
								Appliance		(mbar)		Reading Ratio CO	CO2 Ratio CO		ect Provision tion satisfactory	of flue and termination	Performance test	Serviced	to use	
												ppm	n % ppm	%		satisfactory				
	Bathrooi Cupboar		Boiler	Worcester	8000	Life	RS	Yes	Yes	19.9	30	0.0005 51	8.7 NA NA	NA Ye	s Yes	Yes	Pass	No	Yes	
	Kitchen	า	Oven	Indesit	Unkno	own	FL	Yes	Yes	21.5	7.5	NA NA	NA NA NA	NA Ye	s Yes	NA	NA	No	Yes	
3																				
4																				
5																				
6																				
Defects / Identified										Labels and Warning Notice Issued			CO Alarm	ı(s)		Smoke	e Alarm(s)		
1											No									
2											No		CO Alarm(s) fitted	Yes	Smoke	Alarm(s) fit	ted	Yes	
3																				
5												CO Alarm(s and Satisfa		Pass		Alarm(s) testisfactory	stea	Pass		
6													una Satisia	ctory		una sa	cisiactory			
Emerge	ncy Cor	ntrol Acc	essible Yes Gas	Tightness Satisfactory Ye	25	Comr	ments													
Gas Installation Pipework Visual Inspection Satisfactory Yes																				
Equi	ipotenti	ial Bondii	ng Yes																	
NEXT INSPECTION DUE ON OR 05-Jun-2024 BEFORE																				
b					Received S	Signed						Date		05-Jun-2023						
Print Na	me		Nicky Cass		F	Print Name														