

Serial No
PAD02/

LANDLORD/HOMEOWNER GAS SAFETY RECORD

This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500



Details of Registered Business

Gas Safe Register No: 206115

Registered Engineer's Name: 6-Nick Leedham

Gas Safe Register Licence No: 5222401

Business: N G Plumbing & Heating Ltd

Address: Willow Bank - 4 Waterside, Hemingbrough

Selby

Postcode: YO8 6RD

Contact No: 01757 630633

Details of Site

Name (Mr/Mrs/Miss/Ms):

Address: 182 Hull rd

182 Hull Road, York

Postcode: YO10 3LF

Contact No:

Details of Customer/Landlord

Name (Mr/Mrs/Miss/Ms): Tony Sadler

Address: Tony Sadler

12 Hempland Lane

York

Postcode: YO31 1AX

Contact No: +447904271110

Number of Appliances tested: 1

Appliance Details

	Location of	Type	Manufacturer	Model	Owned by Landlord/Homeowner	Inspected Yes/No	Type of flue
1	Garage	Boiler	Ideal	Logic +c30	Yes	Yes	RS
2							
3							
4							

Inspection Details

	Operating pressure in mbar and/or heat input kW/h or Btu/h	Operation of safety device(s)	Ventilation satisfactory	Visual Condition of flue and termination	Flue operation checks	Combustion analyser reading	Appliance Serviced	CO Alarm Fitted	CO Alarm tested (if Fitted)	SAFE TO USE
1	19.87mb	Pass	Yes	Pass	Pass	Max rate Ratio- 0.0008 Co-74ppm Co2- 9.1% Min rate Ratio- 0.0005 Co-38ppm Co2- 8.1%	Yes	Yes	Yes	Yes
2										
3										
4										

Safety Related Defect(s) Identified

	GIUSP Classification	Warning/Advisory Record insert form serial No*
1		
2		
3		
4		



Remedial Action Taken

1	
2	
3	
4	

Details of Work carried out

Service boiler and carry out landlords gas safety checks

Outcome of gas installation pipework visual inspection	Pass
Outcome of gas supply pipework visual inspection	Pass
Is the Emergency Control Valve access satisfactory?	Pass
Outcome of gas tightness test?	Pass
Is the protective Equipotential bonding satisfactory?	Pass

Record Issued by: N.Leedham	Received by name: Emma
	
Date appliance(s)/flue(s) checked: 17/07/2023	Received by: Tenant

Attention

Next safety check
due by:
02/08/2024