

Landlord Gas Safety Record

Cert. No. 1369

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord							
Eng	jineer	Paul Griffin				Name Tenant								Mr G Mcmanaman						
Company Address		Direct Boiler Co 2				Address	95	95					Company Address							
							La	Lawrence Street						117						
		The Green, Back Street,					Yo	York						Fulford Road						
		Driffield												York						
		Yorkshire					Post Code YO104DZ						Deet Code							
Post Code		YO25 9RW				Tel. No							Post Code	YO104ET						
Tel No.		01759373247											Tel. No							
Gas	s Safe Reg																			
ID (Card No.																			
٩br	oliance D	etails						Inspec	tion Details											
Location				Make	Mode	el	Flue Type	Landlord's Appliance Inspected		Operating Pressure	Heat Input (kW/h)					Visual condition		Appliance	Appliance safe	
								Appliance		(mbar)		Reading Ratio CO	Reading CO2 Ratio CO CO	correct operation	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
_												ppm	% ppm %			satisfactory				
1	Bathroo		Boiler	1ldeal	Logic Com		BF	Yes	Yes	18.57	NA		9.1 0006 49 8.4		Yes	Yes	Pass	Yes	Yes	
2 Kitche		n	Hob	Tbc	Tbo	2	FL	Yes	Yes	NA	5234.59	NA NA	NA NA NA NA	A Yes	Yes	NA	NA	Yes	Yes	
3																				
4																				
5																				
6										Labala a		the last of								
Def	ects / lde	lentified					Labels and Warning Notice Issued					CO Alarm(s)	Smoke	Smoke Alarm(s)						
	1									NA			CO Alarm(c) fitted			Smoke Alarm(s) fitted Yes				
2											NA		CO Alarm(s) fit	tea	Yes	Smoke /	Alarm(s) fitt	ea	Yes	
4													CO Alarm(s) te	sted		Smoke Alarm(s) tested		sted		
													and Satisfactory		Fail		and Satisfactory		NA	
	6																			
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																				
Gas	s Installation	stallation Pipework Visual Inspection Satisfactory Yes Co alarm inoperative.																		
Equipotential Bonding Yes																				
NEXT INSPECTION DUE ON OR 05-Jan-2024																				
BEI	FORE																			
Sia	natures																			
	led by:	Signed	Łw	<u></u>	F	Received S	Signed	6/	/)				Date	05-Ja	in-2023					
						by:		1)6	\neq											
									/											
Prir	nt Name		Paul Griffin		P	Print Name		White	head											