

EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PART 1: DETAILS OF THE CONTRACTOR, CLIENT AND	INSTALLATION	
Registration No: 501766000 Branch No*: 000 Trading Title: Advanced Electrical Services York Ltd Address: York Eco Business Centre, York Amy Johnson Way, York, North Yorkshire	DETAILS OF THE CLIENT Contractor Reference Number (CRN): N/A Name: Adam Bennett Address 58 Gillygate, YORK	DETAILS OF THE INSTALLATION Occupier: Unknown UPRN: N/A Address: 145 Heslington Lane, York, North Yorkshire
Postcode: YO30 4AG Tel No: 01904479485	Postcode: YO31 7EQ Tel No: N/A	Postcode: YO10 4HS Tel No: N/A
PART 2 : PURPOSE OF THE REPORT		
Purpose for which this report is required: Scheduled report prior to property being rented to comply with the Elect	trical safety standard in the private rental sector (England) regulatio	ins as amended
Date(s) when inspection and testing was carried out: (Records available (651.1): () Previous inspection report	available (651.1): (
PART 3 : SUMMARY OF THE CONDITION OF THE INST	ALLATION	
BS7671 Description of premises Dwelling: () Commercial: () Indus Estimated age of electrical installation: () years Evidence of additions or alteratio	strial: (N/A Other (include brief description): N/A	Accessories in good condition. Installation erected to previous version of lation for continued use: Satisfactory /WKS&tisterocory ** (delete as appropriate) this report) and it is recommended that these are acted upon as a matter of urgency.
PART 4 : DECLARATION		
INSPECTION AND TESTING I/We, being the person responsible for the inspection and testing of the electrical installation (a declare that the information in this report, including the observations (PART 5) and the attached Name (capitals) on behalf of the contractor identified in PART 1:	d Schedules, provides an accurate assessment of the condition of the electrical installati Signature:	on taking into account the stated extent and limitations in PART 6 of this report. Date: 10/01/2024
This report is based on the model forms shown in Appendix 6 of <i>BS 7671: 2018+A2:20.</i>		



EICR18.2c

Original (to the person ordering the work)

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PART 5 : OBSERVATIONS					
One of the following Codes, as appropriate, has been allocated to each of the observations made below to indicate to the person(s) responsible for the electrical installation the degree of urgency for remedial action:	Code C1 Danger Present Risk of injury. Immediate remedial action required	Code C2 Potentially Dangerous Urgent remedial action required		Further In	Code FI nvestigation Required
Referring to the Schedule of Items Inspected (see PART 9), the attached Schedule of Circuit Details and Te	est Results (see PART 11A & 11B), and subject t	o any agreed limitations listed in PART	6 -		
No remedial action is required (K), OR The following observations are made:					
	Observation(s)			Code	Location Reference
(.1) (4.6 Consumer units manufactured from flammable materials (PVC) and I				()	(Understairs)
(2) (4.144.17 RCDs/RCBOs in the consumer unit are type AC (possible DC k				(.C3)	(Consumer unit)
(.3) (4.164.19 Absence of Arc fault protection for socket circuits (HMO property				(.C3)	(Installation)
(.4) (Absence of Surge Protective Device (SPD) where required by 443.4	.1 i-iii)	(.C3)	(Installation)
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() ()	()	()
() (,	()	()
		A		page numbers	
Immediate remedial action required for items: (.N/A	,	ment recommended for items:	(. 1,2,3,4		
Urgent remedial action required for items: (.N/A) Further	investigation required for items:	(.N/A)



EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 – Requirements for Electrical Installations

PART 6 : DETAILS AND LIMITATIONS OF THE INSPECTION AND TESTING The inspection and testing has been carried out in accordance with BS 7671: 2018, as amended to 2022...... (date). Cables concealed within trunking and conduits, or cables and conduits concealed under floors, in inaccessible roof spaces and generally within the fabric of the building or underground, have not been visually inspected unless specifically agreed between the Client and the Inspector prior to inspection. Details of the electrical installation covered by this report: All circuits within the installation have been tested and inspected. (see additional page No.N/A Agreed limitations including the reasons, if any, on the inspection and testing (653.2); No live to neutral insulation resistance tests carried out to prevent damage to connected equipment. No test or inspection has been undertaken in any building voids/loft spaces. see continuation sheet for more... Agreed with (print name): CLIENT A minimum of 20% of accessories have been visually checked for compliance (see additional page No.N/A ...) Extent of sampling: Operational limitations including the reasons: Unable to determine size and type of main supply company fuse as unit is sealed and access forbidden (see additional page No. N/A ...) PART 7 : SUPPLY CHARACTERISTICS AND EARTHING ARRANGEMENTS System type and earthing arrangements Number and type of live conductors Nature of supply parameters ^[1] By enquiry 2-phase, 3-wire: (N/A TN-C: (N/A TN-C-S; (N/A ...) AC 1-phase, 2-wire; (.....) ^[2] By enquiry or by Nominal voltage between lines, U^[1]: (N/A) V 3-phase, 3-wire: (N/A 3-phase, 4-wire: (N/A measurement IT: (N/A) (230...) V Nominal line voltage to Earth, U_{0} ^[1]: TT: (N/A Other: (N/A 3-wire: (N/A ...) (50) Hz DC 2-wire; (N/A ...) Nominal frequency, f [1]: Supply protective device (....) (0.95 ...) kA Confirmation of supply polarity: Prospective fault current, Inf [2]*: BS FN: (Non-verifiable) Type; (N/A Rated current: (N/A) A Page No: (N/A (0.3) 0 Other sources of supply (Schedule of Test Results) External earth fault loop impedance, Z_{α} ^[2]*: PART 8 : PARTICULARS OF INSTALLATION REFERRED TO IN THIS REPORT Maximum demand (load): (45.....) XXX/A Main protective conductors Main protective bonding connections Main switch / Switch-fuse / Circuit-breaker / RCD (delete as appropriate) Earthing conductor: Water installation pipes: Location: (Within consumer unit Means of Earthing (material Copper Gas installation pipes: BS EN: (60947-3) Type: (3.....)) Rating / setting of device: (N/A....) A Distributor's facility: (N/A csa (16...) mm² Connection/continuity Structural steel: No. of poles; (2.....) Current rating: (100....) A Voltage rating: (230....) V (N/A) Installation earth electrode(s): ₍N/A Oil installation pipes: Earth electrode type - rod(s), tape, etc: Main protective bonding conductors: ₍N/A Lightning protection: Where an RCD is used as the main switch (None...) (material Copper) Other (state): RCD Type: (N/A....) RCD rated residual operating current, I_{AB} : (N/A....) mA Location: (N/A N/A (N/A csa (1.0....) mm² Connection/continuity Rated time delay: (N/A....) ms Measured operating time: (N/A....) ms (N/A...)Ω Electrode resistance to Earth: N/A (N/A)

*Where the installation is supplied by more than one source, the higher or highest values of prospective fault current, Inf, and external earth fault loop impedance, Ze, must be recorded.

All fields must be completed. Enter either, as appropriate: '\screw' if Acceptable condition; 'N/A' if Not applicable; 'LIM' if a Limitation exists, or Code appropriately: CODE 'C1', 'C2', 'C3' or 'FI' (codes to be recorded in PART 5, with additional comments (where appropriate) on attached numbered sheets)



EICR18.2c

Original (to the person ordering the work)

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

.0 Intake equipment (visual inspection only)		•	Accessibility of all protective bonding connections (543.3.2)	()	4.16	Confirmation that integral test button / switch, where present,	
In outcome against an item in section 1.1, other than access to live parts, should not b		•	Provision of earthing / bonding labels at all appropriate locations (514.13.1)	(causes AFDD to trip when operated (643.10)	(<u>C3</u>
letermine the overall assessment of the installation. Where inadequacies are identifi hould be put against the appropriate item and a comment made in Part 5 of this repo	-			(N/A)	4.17	Presence of diagrams, charts or schedules at or near equipment, where required (514.9.1)	(
1 Distributor / supplier intake equipment			Other methods of protection		4.18	Presence of alternative supply warning notice at or near equipment,	
Service cable	()		e any of the methods listed below are employed, details should be provided on separate			where required (514.15)	(N/A
Service head	()		Non-conducting location (418.1)	(N/A)	4.19	Presence of next inspection recommendation label,	
Earthing arrangement	()			(N/A)		where required (514.12.1)	(!
Meter tails	()			(N/A)	4.20	Presence of other required labelling (please specify) (514)	(<u>N/A</u>
Metering equipment	()	•		(N/A)	4.21	Compatibility of protective devices, bases and other components;	
Isolator, where present	(N/A)	•		(<u>N/A</u>)		correct type and rating (no signs of unacceptable thermal damage, arcing or overheating) (432; 433; 434)	(•
here inadequacies in the intake equipment are encountered, which may result in a danger		·	Provisions where automatic disconnection of supply is not feasible (419)	(N/A)	1 22	Single-pole switching or protective devices in line conductors only	(
tentially dangerous situation, the person ordering the work and / or dutyholder must be ir is strongly recommended that the person ordering the work informs the appropriate autho		4.0	Distribution equipment, including consumer units and distribution bo	ards	7,22	(132.14.1; 530.3.3)	(
	.N/Δ .	4.1	Adequacy of working space / accessibility to equipment (132.12; 513.1)	(•	4.23	Protection against mechanical damage where cables enter equipment	
2 Consumer's isolator, where present	()	4.2	Security of fixing (134.1.1)	()		(522.8.1; 522.8.5; 522.8.11)	(
3 Consumer's meter tails	()	4.3	Condition of insulation of live parts (416.1)	()	4.24	Protection against electromagnetic effects where cables enter	
.0 Presence of adequate arrangements for parallel or switched alternativ	e sources	4.4	Adequacy security of barriers or enclosures (416.2.3)	()		ferromagnetic enclosures (521.5.1)	(
Adequate arrangements where a generating set operates as a switched	NI/A	4.5		()	5.0	Distribution circuits	
alternative to the public supply (551.6)	(N/A)	4.6	Condition of enclosure(s) in terms of fire rating, etc. (421.1.201; 421.1.6; 526.5)	(C3)	5.1	Identification of conductors (514.3)	(N/A
 Adequate arrangements where a generating set operates in parallel with the public supply (551.7) 	(N/A	4.7	Enclosure not damaged / deteriorated so as to impair safety (651.2)	()	5.2	Cables correctly supported throughout their run (521.10.202; 522.8.5)	(N/A
	()	4.8	Presence and effectiveness of obstacles (417.2)	(•	5.3	Condition of insulation of live parts (416.1)	(N/A
0 Methods of protection		4.9	Presence of main switch(es), linked where required (462.1; 462.1.201; 462.2)	(5.4	Non-sheathed cables protected by enclosure in conduit, ducting or	-
1 Automatic disconnection of supply (ADS)		4.10	Operation of main switch(es) (functional check) (643.10)	(trunking (521.10.1)	(N/A
 Main earthing / bonding arrangement (411.3; Chap. 54) 	()	4.11	Manual operation of circuit-breakers, RCDs and AFDDs to prove		5.5	Suitability of containment systems for continued use	
 Presence of distributor's earthing arrangement (542.1.2.1; 542.1.2.2), or 	(/)		functionality (643.10)	()		(including flexible conduit) (522)	(N/A
presence of installation earth electrode arrangement (542.1.2.3)	() ()	4.12	Confirmation that integral test button / switch causes RCD(s) to trip		5.6	Cables correctly terminated in enclosures (526)	(N/A
Adequacy of earthing conductor size (542.3; 543.1.)	() ()		,	()	5.7	Confirmation that ALL conductor connections, including connections to	NI/4
Adequacy of earthing conductor connections (542.3.2)	() ()	4.13	RCD(s) provided for fault protection - includes RCBOs	(N/A)		busbars, are correctly located in terminals and are tight and secure (526.1)	(N/A
Accessibility of earthing conductor connections (543.3.2)	(v) (v)	414		()	5.8	Examination of cables for signs of unacceptable thermal or mechanical	(N/A
Adequacy of main protective bonding conductor sizes (544.1.1)	(•)	4.14	RCD(s) provided for additional protection / requirements, where required - includes RCB0s (411.3.3; 415.1)	(C3	F 0	damage / deterioration (421.1; 522.6)	•
 Adequacy and location of main protective bonding conductor 			נוטוד נטטטווד) טטעטו איז איז	()	5.9	Adequacy of cables for current-carrying capacity with regard for the type	(N/A

This report is based on the model forms shown in Appendix 6 of *BS 7671: 2018+A2:2022* @ Copyright Certsure LLP (May 2023)



EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

.10	Adequacy of protective devices; type and rated current for fault protection (411.3)	(N/A		Cables correctly supported throughout their run (521.10.202; 522.8.5)	() ()	•	*For cables concealed in walls / partitions containing metal parts regardless of depth (522.6.203)	(N/A
.11	Presence and adequacy of circuit protective conductors (411.3.1.1; 543.1)	(N/A (N/A))			()		*For final circuits supplying luminaires within domestic (household)	(
12	Coordination between conductors and overload protective devices		6.4	Non-sheathed cables protected by enclosure in conduit, ducting or trunking (521.10.1)	(N/A		premises (411.3.4)	(
	(433.1; 533.2.1)	(N/A ()	6.5	Suitability of containment systems for continued use		* 014	n installations designed minute DC 7671, 2010 manualt base serviced DCDs for addition	
13	Cable installation methods / practices with regard to the type and nature of	N/A		(including flexible conduit) (522)	()		er installations designed prior to BS 7671: 2018 may not have required RCDs for additiona Provision of fire barriers, sealing arrangements and protection against	ai protec
	installation and external influences (522)	() (N/A ()	6.6	Adequacy of cables for current-carrying capacity with regard for the type		0.14	thermal effects (527)	(
	Where exposed to direct sunlight, cable of a suitable type (522.11.1)	()		and nature of installation (523)	()	6.15	Band II cables segregated / separated from Band I cables (528.1)	(
5	Cables concealed under floors, above ceilings, in walls / partitions, adequately protected against damage (522.6.201; 522.6.202;		6.7	Adequacy of protective devices; type and rated current for fault protection (411.3)	(6.16	Cables segregated / separated from non-electrical services (528.3)	(
	522.6.203; 522.6.204) -		6.8	Presence and adequacy of circuit protective conductors (411.3.1.1; 543.1)	(V)	6.17	Termination of cables at enclosures - identify / record numbers and	
•	Installed in prescribed zones (see Section D. <i>Extent and limitations</i>) (522.6.202)	(N/A	6.9	Co-ordination between conductors and overload protective devices			locations of items inspected (526) – Connection under no undue strain (526.6)	(
	(322.6.202) Incorporating earthed armour or sheath, or run within earthed wiring	()		(433.1; 533.2.1)	()		No basic insulation of a conductor visible outside enclosure (526.8)	(
	system, or otherwise protected against mechanical damage by nails,		6.10	Wiring system(s) appropriate for the type and nature of the installation and external influences (522)	()		Connections of live conductors adequately enclosed (526.5)	(
	screws and the like (see Section D) (522.6.201; 522.6.204)	(N/A ()	6.11	Where exposed to direct sunlight, cable of a suitable type (522.11.1)	()		Adequately connected at point of entry to enclosure (glands, bushes, etc.)	
	Provision of fire barriers, sealing arrangements and protection against	,N/Α		Cables concealed under floors, above ceilings, in walls / partitions,	()		(522.8.5)	, (
,	thermal effects (527)	() .N/A		adequately protected against damage (522.6.201; 522.6.202;		6.18	Condition of accessories including socket-outlets, switches and joint	
	Band II cables segregated / separated from Band I cables (528.1)	() (N/A ()		522.6.203; 522.6.204) -			boxes (651.2)	(
	Cables segregated / separated from non-electrical services (528.3)	N/A	•	Installed in prescribed zones (see Section D. <i>Extent and limitations</i>)	LIM ,	6.19		(
)	Condition of circuit accessories (651.2) Suitability of circuit accessories for external influences (512.2)	() (N/A ()		(522.6.202) Incorporating earthed armour or sheath, or run within earthed wiring	()	6.20	Single-pole switching or protective devices in line conductors only (132.14.1; 530.3.3)	(
	Single-pole switching or protective devices in line conductors only	()	-	system, or otherwise protected against mechanical damage by nails,				(
	(132.14.1; 530.3.3)	(N/A ()		screws and the like (see Section D) (522.6.201; 522.6.204)	(N/A ()	7.0	Isolation and switching Isolators -	
2	Adequacy of connections, including cpcs, within accessories and to		6.13	Provision of additional protection by RCD having rated residual operating		7.1	Presence and condition of appropriate devices (462; 537.2)	(
	fixed and stationary equipment - identify / record numbers and	(N/A ()		current not exceeding 30 mA -	(Acceptable location - state if local or remote from equipment in question	(
2	locations of items inspected (526)	()		*For all socket-outlets of rating 32 A or less (411.3.3) tional protection by RCD may not have been provided as a noted exception in	()		(462; 537.2.7)	(
5	Presence, operation and correct location of appropriate devices for isolation and switching (Chap. 46; 537)	N/A ()		in non-domestic installations covered by indent (ii) of Regulation 411.3.3.		•	Capable of being secured in the OFF position (462.3)	(
	General condition of wiring system (651.2)	N/A ()	•	*For the supply of mobile equipment not exceeding 32 A rating		•	Correct operation verified (643.10)	(
5	Temperature rating of cable insulation (522.1.1; Table 52.1)	N/A ()		for use outdoors (411.3.3)	()	•	Clearly identified by position and / or durable marking (537.2.7)	(
)	Final circuits		•	*For cables concealed in walls at a depth of less than 50 mm	()	•	Warning label posted in situations where live parts cannot be isolated	,N//
	Identification of conductors (514.3)	(V)		(522.6.202)	()		by the operation of a single device (514.11.1; 537.1.2)	(

This report is based on the model forms shown in Appendix 6 of *BS 7671: 2018+A2:2022* @ Copyright Certsure LLP (May 2023)



EICR18.2c

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PA	RT 9 : SCHEDULE OF ITEMS INSPECTED (er	nter 🗸 , N/	Aor	Classification Code C1, C2, C3 or FI, as applicable)				
7.2	Switching off for mechanical maintenance – Presence and condition of appropriate devices (464.1; 537.3.2)	()	8.5 8.6	Security of fixing (134.1.1) Cable entry holes in ceiling above luminaires, sized or sealed so as to	(/)	•	Low voltage (e.g. 230 volt) socket-outlets sited at least 2.5 m from zone 1 (701.512.3)	(N/A
	Capable of being secured in the OFF position where not under continuous supervision (464.2)	(v)	0.0	restrict the spread of fire: list number and location of luminaires inspected (separate page) (527.2)	()	•	Suitability of equipment for external influences for installed location in terms of IP rating (701.512.2)	()
	Correct operation verified (643.10)	(/) (/)	8.7 •	Recessed luminaires (downlighters) – Correct type of lamps fitted (559.3.1)	(N/A)	•	Suitability of accessories and controlgear etc. for a particular zone (701.512.3)	()
7 .3	Clearly identified by position and / or durable marking (537.3.2.4) Emergency switching off –		•	Installed to minimise build-up of heat by use of "fire rated" fittings, insulation displacement box or similar (421.1.2)	, N/Α ,	•	Suitability of current-using equipment for particular position within the location (701.55)	()
	Presence and condition of appropriate devices (465; 537.3.3; 537.4) Readily accessible for operation where danger might occur (537.3.3.6)	(N/A () (N/A ()		No signs of overheating to surrounding building fabric (559.4.1)	() (N/A () (N/A	9.2	Other special installations or locations – N/A	₍ Ν/Α)
	Correct operation verified (643.10)	(N/A ()	9.0	No signs of overheating to conductors / terminations (526.1) Special locations and installations	()			() ()
	Clearly identified by position and / or durable marking (537.3.3.5; 537.3.3.6; 537.4.3; 537.4.4)	(N/A ()	When	e special installations or locations relating to a particular Section of Part 7, an additiona	l Inspection			() ()
7.4 ∎	Functional switching – Presence and condition of appropriate devices (537.3.1.1; 537.3.1.2)	()	9.1	dule(s) should be provided on separate pages. Location(s) containing a bath or shower –				()
•	Correct operation verified (643.10)	()	•	Additional protection by RCD having rated residual operating current not exceeding 30 mA for all low voltage (LV) circuits serving the location or		10.0	Prosumer's low voltage installation	(<u>N/A</u>)
8.0	Current-using equipment (permanently connected)			passing through zones 1 and / or 2 of the location (701.411.3.3)	()		re elements of a prosuming installation falling within the scope of Chapter 82 are cove. rt, additional schedules detailing the associated inspection and testing should be pro	-
8.1	Condition of equipment in terms of IP rating, etc. (416.2; 422.3; 422.4; 522.4)	()	•	Where used as a protective measure, requirements for SELV or PELV met (701.414.4.5)	N/A	1 '	r, aduitional schedules detailing the associated inspection and testing should be pro rate pages.	
8.2	Equipment does not constitute a fire hazard (421)	()	•	Shaver supply units complying with BS EN 61558-2-5 formerly BS 3535		Sch	edule of Items Inspected by	
8.3	Enclosure not damaged / deteriorated so as to impair safety			(701.512.3)	(N/A ()	Nam	ne (capitals): THOMAS BURDETT	
8.4	(134.1.1; 416.2) Suitability for the environment and external influences (512.2)	() ()	•	Presence of supplementary bonding conductors, unless not required by <i>BS 7671: 2018</i> (701.415.2)	(N/A ()	Sign	nature: Date: Date:	

PART 10 : SCHEDULES AND ADDITIONAL PAGES (the pages identified are an essential part of this report (see Regulation 653.2))

Schedule of Inspections	Schedule of Circuit Details and Test	Additional pages, including data sheets	Special installations or locations	Schedules relating to Prosumer's	Continuation sheets
	Results for the installation	for additional sources	(indicated in item 9.2 above)	installations (indicated in item 10 above)	
Page No(s): (Page No(s): (Page No(s): (11)	Page No(s): (None)	Page No(s): (None)	Page No(s): (None)



ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

PA	RT 11A : SCHEDULE OF CIRCUIT DETAILS	6 (GO TO	Part 11B '	Schedule	of Test R	lesults' to	enter te	st results for the	e corresp	oonding c	ircuit liste	d in this pa	art)			
		(IIB)	p	erved		conductor er & csa)	action (71)		Overcurr	ent protective de	evice			RCD		
Circuit number	Circuit description	Type of wiring (see footer to PART 11B)	Reference Method (BS 7671)	Number of points served	Live (mm²)	срс (mm²)	නි Max. disconnection කි time (BS 7671)	BS (EN)	Туре	Rating (A)	Short- circuit capacity (kA)	Maximum permitted <i>Zs</i> * (Ω)	BS (EN)	Туре	Rating (A)	Operating current, I _{dn} (mA)
	RCD main switch	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	80	30
	RCD main switch	N/A	N/A	N/A	N/A		0.4	N/A	N/A		N/A	N/A	61008	AC	80	30
1	Extension 1st floor lights	A	101	2	1	1	0.4	60898	в	6	6	7.28	N/A	N/A	N/A	N/A
2	House lighting	A	101	11	1	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A
3	Ext bedroom sockets	A	С	2	4	1.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A
4	House sockets	A	с	18	2.5	1.5	0.4	60898	в	32	6	1.37	N/A	N/A	N/A	N/A
5	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
6	Immersion heater	A	с	2	2.5	1.5	0.4	60898	В	16	6	2.73	N/A	N/A	N/A	N/A
7	Cooker hood	A	С	1	2.5	1.5	0.4	60898	В	10	6	4.37	N/A	N/A	N/A	N/A
8	Cooker	A	С	1	6	2.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A
\vdash																
DB o Loc Con SPE	STRIBUTION BOARD (DB) DETAILS (complete in every c Idesignation: DB-01 ation of DB: Understairs Z_{db} : 0.3 (Ω) I_{pf} at DB+0.95 firmation of supply polarity: (,) P Details** Types: T1 (N/A) T2 (N/A) N/A us indicator checked (where functionality indicator is present):	(kA) (N/A) (N/A)	device is Type brac Where T3 to protect details in (See Sect	mbined T1 installed, in kets. devices ar sensitive e 'Comments ion 534 for	+ T2 or T2 · dicate by ti e installed o quipment, o s' (PART 11E further det bs have visil	cking both on a circuit enter s), ails).	Supply to Overcurr BS (EN): (Associate	COMPLETED ONLY DB is from: N/A ent protective devic N/A ed RCD (if any) N/A	e for the d) Type:	istribution c	ircuit Nominal vol [.]	age: (N/A	.) V Rating: (N/A)A N	No. of phases	s: (<u>N/A</u>)

This report is based on the model forms shown in Appendix 6 of *BS 7671*: 2018+A2:2022 @ Copyright Certsure LLP (May 2023) Enter a (✓) or value in the respective fields, as appropriate. Where an item is not applicable insert N/A
[†] Where applicable. *Where figure is not taken from *BS 7671*, state source: N/A....

EICR18.2c

Page 7 of 11



ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

			Continuity (ם)		Ins	ulation resista	ance		2s Zs	R	CD	AFDD**			
		ing final circuits neasured end to		(complete	ircuits at least one umn)	Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth fault loop impedance, Zs	Operating time*	Test button	AFDD test button		Comments and additional informat	ion, where required
	(Line) r ₁	(Neutral) r _n	(cpc) r ₂	(R ₁ + R ₂)	R ₂	(MΩ)	(MΩ)	(V)	(⁄)	(Ω)	(ms)	(🗸)	(⁄)			
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	29	V	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	v	N/A	29	V	N/A	N/A		
	N/A	N/A	N/A	0.56	N/A	LIM	30	500	V	0.86	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.76	N/A	LIM	30	500	~	1.06	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.14	N/A	LIM	30	500	~	0.44	N/A	N/A	N/A	N/A		
	0.54	0.54	0.64	0.39	N/A	LIM	30	500	~	0.58	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.16	N/A	LIM	30	500	V	0.46	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.15	N/A	LIM	30	500	v	0.45	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.11	N/A	LIM	30	500	V	0.41	N/A	N/A	N/A	N/A		
		_														
		_														
	uits/equipn	nent vulneral	ole to damag	e when testir	ng (where ap	plicable): N/	A									
_															~~	
	STED BY	Name	(capitals): T	HOMAS E	BURDETT	-			Positio	n: Electric	ian			Signature: .~	THR	Date: 10/01/2024
-	ST INSTR		ENTER SE	RIAL NUN	IBER AGA	INST EACH	I INSTRUM	IENT USE))							
	lti-function:		(inuity:			Insulatio	-	ance:		Ear	th fault lo	op impedance:	Earth electrode resistance:	RCD:
	2092619	2 A		Ν/Δ	,			N/A				N/		·F ····F · · ····	N/A	N/A
·																
J	enectiver	ness is veri	ied using a	n alternating	g current te	est at rated	residual ope	erating curre	ent $(I_{\Delta n})$						unction. where a circuit contains an <i>i</i> on, where required' column.	AFDD this should be stated in the field for
			Thermoplast	tic insulated	- Thermon	astic cables	Thermopla	stic cables	- The	rmonlastic cable		hermoplastic		r	· · · · · · · · · · · · · · · · · · ·	N/A
	S for Type of	f wiring (A) / sheathed o	ables (B) Thermopl in metalli	c conduit	C) Thermopla in non-me	tallic conduit	D) The in n	rmoplastic cable netallic trunking	s (E) T	on-metallic tr	unking	(F) Thermoplastic / SWA cables	(G) Thermosetting / SWA cables (H) Miner	ral-insulated cables Other (state): N/A

EICR18.2c



ISN18.2c

CONTINUATION SHEET : EIC and EICR

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

P	ART A : SCHEDULE OF CIRCUIT DETAILS (GO TO P	art B 'Sch	edule of	Test Resu	ilts' to ent	er test re	sults for the co	rrespond	ding circu	it listed in	this part)				
		[B)	Ð	rved		conductor er & csa)	ction 71)		Overcurr	ent protective de	evice			RCD		
Circuit number	Circuit description	Type of wiring (see footer to PART B)	Reference Method (BS7671)	Number of points served	Live (mm ²)	cpc (mm²)	නි Max. disconnection කි time (BS 7671)	BS (EN)	Туре	Rating (A)	Short- circuit capacity (kA)	Maximum permitted Zs* (Ω)	BS (EN)	Туре	Rating (A)	Operating current, I _{dn} (mA)
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30
	RCD	N/A	N/A	N/A	N/A		0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30
1	Cooker	A	с	1	6		0.4	60898	в	32	6	1.37	N/A	N/A	N/A	N/A
2	Sockets	A	с	5	4		0.4	60898	в	32	6		N/A	N/A	N/A	N/A
3	Smoke alarms	A	101	11	1	1	0.4	60898	В	6	6	7.28	N/A	N/A	N/A	N/A
4	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
5	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30
	RCD	N/A	N/A	N/A	N/A	N/A	0.4	N/A	N/A	N/A	N/A	N/A	61008	AC	63	30
6	Shower	А	с	1	6	2.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A
7	Hob	А	С	1	6	2.5	0.4	60898	В	32	6	1.37	N/A	N/A	N/A	N/A
8	Lighting	A	с	6	1	1	0.4	60898	в	6	6	7.28	N/A	N/A	N/A	N/A
9	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
10	Spare	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
DB Lo Co SP	STRIBUTION BOARD (DB) DETAILS (complete in every c designation: DB -02 cation of DB: Understairs Z_{db} ; 0.3 (Ω) I_{pf} at $DB^+0.95$ nfirmation of supply polarity: (,) Phase sequence confirmed [†] : D Details** Types: TI (N/A) T2 (N/A) T3 (N/A) N/A atus indicator checked (where functionality indicator is present):	(kA) (N/A) (N/A)	device is Type brac Where T3 to protect details in (See Sect	mbined T1 installed, in kets. devices ar sensitive e 'Comments ion 534 for	e installed quipment, s' (PART B), further det	cking both on a circuit enter ails).	Supply to Overcurr BS (EN): (Associate	COMPLETED ONLY DB is from: N/A ent protective devic N/A ed RCD (if any) N/A	e for the d) Type:	istribution c	ircuit Nominal vol ¹	tage: (N/A	.) V Rating: (N/A)A N	No. of phases	s: (<mark>N/A</mark>)

This schedule is based on the model forms shown in Appendix 6 of *BS 7671*: 2018+A2:2022 Enter a (✓) or value in the respective fields, as appropriate. Where an item is not applicable insert N/A [†] Where applicable. *Where figure is not taken from *BS 7671*, state source: N/A

9 Page of

11



ISN18.2c

CONTINUATION SHEET : EIC and EICR

Issued in accordance with BS 7671: 2018+A2:2022 - Requirements for Electrical Installations

			Continuity (1)		In	sulation resist	ance		oop ,Zs	R	CD	AFDD**			
circuit number		Ring final circuit measured end to		(complet	circuits e at least one lumn)	Live / Live	Live / Earth	Test voltage DC	Polarity	Max. measured earth fault loop impedance, Zs	Operating time*	Test button	AFDD test button		Comments and additional information	n, where required
	(Line) r ₁	(Neutral) r _n	(cpc) r ₂	(R ₁ + R ₂)	R ₂	(MΩ)	(MΩ)	(V)	()	(Ω)	(ms)	(√)	(√)			
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	35.9	~	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	35.9	V	N/A	N/A		
	N/A	N/A	N/A	0.15	N/A	LIM	100	500	V	0.45	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.70	N/A	LIM	100	500	V	0.53	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	1.70	N/A	LIM	100	500	~	2.00	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	28.3	~	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	V	N/A	28.3	V	N/A	N/A		
	N/A	N/A	N/A	0.17	N/A	LIM	100	500	V	0.47	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.15	N/A	LIM	100	500	V	0.45	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	0.67	N/A	LIM	100	500	V	0.97	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A		
		_														
_																
2	uits/equipr	ment vulnera	ble to damag	e when testi	ng (where a	oplicable): N	/A									
E	STED BY	Name	(capitals):	HOMAS	BURDET	l			Positio	n: Electric	cian			Signature: .	44B)-	Date: 10/01/2024
E	ST INSTR	RUMENTS	(ENTER SE	RIAL NUN	IBER AGA	INST EAC	H INSTRUM	IENT USE	D)							
u	lti-function:	:		Cont	inuity:			Insulati	on resist	ance:		Ear	rth fault lo	op impedance:	Earth electrode resistance:	RCD:
C	2092619	9		N/A	•••••••••••••••••••••••••••••••••••••••			N/A				<u>N/</u>	Ά		N/A	<u>N/A</u>
:0) effective	ness is veri	fied using a	n alternatin	g current te	est at rated	residual op	erating curr	ent (I _{An})	** Where	e installec	d. Note, n	ot all AFDDs have a test fun	ction. Where a circuit contains an A	FDD this should be stated in the field for t
											circuit	in the 'C	omments	and additional information,	where required' column.	
E	S for Type o	of wiring (A) Thermoplast / sheathed c	ic insulated ((B) Thermop in metall	lastic cables ic conduit		astic cables tallic conduit	(D) Th in	ermoplastic cable metallic trunking	es (E)	hermoplastic non-metallic tr	cables in runking	(F) Thermoplastic / SWA cables ((i) Thermosetting / SWA cables (H) Minera	l-insulated cables Other (state):N/A
•							7671: 2018+	· · · ·						n the respective fields, as an	· · · ·	



N18.2c

GENERAL CONTINUATION SHEET

Issued in accordance with BS 7671: 2018+A2:2022 – Requirements for Electrical Installations

NOTES

Agreed limitations

Accessories such as sockets and light switches not unscrewed where decor may be damaged.

Fixed equipment such as cookers, or other hard wired equipment tested at point of isolation.

Socket-outlets or connection points behind washing-machines, dishwashers, cooker-hoods etc not inspected or tested.

Only wiring that can be reasonably accessed has been visually inspected.

Circuits incorporating integrated appliances only tested at isolation spur unit and not at socket outlet behind appliance to prevent damage to goods and floor areas where moving would be required.

Central heating system including wiring to thermostats and control / wiring centres not inspected - tested to isolation point only.

Zs values may be calculated to prevent access to exposed live parts during testing

Unable to determine whether cables are routed in prescribed cable zones due to building fabric (plaster etc)

NOTES FOR RECIPIENT

THIS CONDITION REPORT IS AN IMPORTANT AND VALUABLE DOCUMENT WHICH SHOULD BE RETAINED FOR FUTURE USE

The purpose of periodic inspection is to determine, so far as is reasonably practicable, whether an electrical installation is in a satisfactory condition for continued service. This report provides an assessment of the condition of the electrical installation identified overleaf at the time it was inspected and tested, taking into account the stated extent of the installation and the limitations of the inspection and testing.

This report has been issued in accordance with the national standard for the safety of electrical installations, BS 7671: 2018+A2:2022 – Requirements for Electrical Installations.

The report identifies any damage, deterioration, defects and/or conditions found by the inspector which may give rise to danger (see PART 5), together with any items for which improvement is recommended.

You should have received the report marked 'Original' and the contractor should retain a duplicate. If you were the person ordering this report, but not the owner or user of the installation, you should pass this report, or a full copy of it, including these notes, the schedules and additional pages (if any), immediately to the owner or user of the installation.

This report should be retained in a safe place and shown to any person inspecting or undertaking further work on the electrical installation in the future. If you later vacate the property, this report will provide the new user with an assessment of the condition of the electrical installation at the time the periodic inspection was carried out.

For safety reasons, the electrical installation should be re-inspected at appropriate intervals by a skilled person or persons, competent in such work. NICEIC* recommends that you engage the services of an NICEIC contractor for the inspection. Only an NICEIC contractor is authorised to issue this NICEIC Electrical Installation Condition Report, which has a unique serial number that is traceable to the contractor to which it was supplied by NICEIC.

The recommended date by which the next inspection should be carried out is stated in PART 4 of this report. With the exception of domestic (household) premises, there should also be a notice at or near the main switchboard or distribution board/consumer unit indicating when the next inspection of the installation is due.

This report is intended to be issued only for the purpose of reporting on the condition of an existing electrical installation and must not be issued to certify new electrical installation work including the replacement of a distribution board or consumer unit.

The report consists of at least eight numbered pages. The report is only valid if the Schedule of Items Inspected (PART 9) has been completed to confirm that all relevant inspections have been carried out and the Schedule of Circuit Details (PART 11A) and the Schedule of Test Results (PART 11B) are attached. For installations having more than one distribution board (or consumer unit) or more circuits than can be recorded in PARTS 11A & 11B, one or more additional Schedule of Circuit Details and Schedule of Test Results, should form part of the report. Additional numbered pages may have been provided to permit further relevant information relating to the installation to be recorded. The report is invalid if any of the additional pages, listed in PART 10 are missing.

Where the installation includes a residual current device (RCD) it should be tested every six months by pressing the button marked "T" or "Test". The device should switch off the supply and should then be switched on to restore the supply. If the device does not switch off the supply when the button is pressed, seek expert advice. For safety reasons it is important that this instruction is followed.

Where the installation includes an arc fault detection device (AFDD) having a manual test facility it should be tested six-monthly by pressing the test button. Where an AFDD has both a test button and automatic test function, manufacturer's instructions should be followed with respect to test button operation.

Where the installation includes a surge protection device (SPD) the status indicator should be checked to confirm it is in operational condition in accordance with manufacturer's information. If the indication shows that the device is not operational, seek expert advice.

Where the installation can be supplied by more than one source, such as the public supply and a standby generator or microgenerator, this should be identified in PART 7 Supply Characteristics and Earthing Arrangements, and the Schedules of Circuit Details and Test Results (PART 11A & 11B) compiled accordingly.

PART 6 (Details and limitations) should identify fully the extent of the installation covered by this report and any limitations on the inspection and testing. The inspector should have agreed these aspects with the person ordering the report and with other interested parties (licensing authority, insurance company, mortgage provider and the like) before the inspection was carried out.

Operational limitations may have been encountered during the inspection such as inability to gain access to parts of the installation or to an item of equipment. The inspector should have noted any such limitations in PART 6. It should be noted that the greater the limitations applying to a report, the less its value from the safety aspect.

A declaration should have been given by the inspector in PART 4 of the report. The declaration must reflect the statement given in PART 3, which summarises the observations and recommendations made in PART 5. Where one or more observations have been made in PART 5, the Classification code given to each by the inspector indicates the degree of urgency with which remedial action needs to be taken to restore the installation to a safe working condition.

Where the inspector has indicated an observation as code C1 (danger present) the safety of those using the installation is at risk. Wherever practicable, items classified as C1 should be made safe on discovery, and it is recommended that a skilled person(s) competent in electrical installation work undertakes the necessary remedial work immediately.

Where the inspector has indicated an observation as code C2 (potentially dangerous) the safety of those using the installation may be at risk, and it is recommended that a skilled person competent in electrical installation work undertakes the necessary remedial work as a matter of urgency.

Where the inspector has indicated that an item requires further investigation (FI), the investigation should be carried out without delay to determine whether danger or potential danger exists. For further guidance on the Classification codes, please see the reverse of page 2.

Where inadequacies in the intake equipment have been observed (Item 1 of PART 9), the person ordering the inspection should inform the distributor and/or supplier as appropriate.

Should the person ordering this report have reason to believe that it does not reasonably reflect the condition of the electrical installation reported on, that person should in the first instance raise the specific concerns in writing with the contractor. If the concerns remain unresolved, the person ordering this report may make a formal complaint to NICEIC, for which purpose a complaint form is available on request.

The complaints procedure offered by NICEIC is subject to certain terms and conditions, full details of which are available upon application. NICEIC does not investigate complaints relating to the operational performance of electrical installations (such as lighting levels), or to contractual or commercial issues (such as time or cost).

For further information about electrical safety and how NICEIC can help you, visit: WWW.NICEIC.com

* NICEIC is operated by Certsure LLP, a partnership between the Electrical Contractors' Association and the charity, Electrical Safety First. NICEIC maintains and publishes registers of electrical contractors that it has assessed against particular scheme requirements (including the technical standard of electrical work).

GUIDANCE FOR RECIPIENTS ON THE CLASSIFICATION CODES ONLY ONE CLASSIFICATION CODE SHOULD BE GIVEN FOR EACH RECORDED OBSERVATION

Classification code C1 (Danger present)

Where an observation has been given a Classification code C1, the safety of those using the installation is at risk and immediate remedial action is required.

The person responsible for the maintenance of the installation is advised to take action without delay to remedy the observed deficiency in the installation, or to take other appropriate action (such as switching off and isolating the affected part(s) of the installation) to remove the danger. The NICEIC contractor issuing this report will be able to provide further advice.

NICEIC makes available 'Electrical Danger Notification' forms to enable inspectors to record, and then to communicate to the person ordering the report, any dangerous condition discovered.

Classification code C2 (Potentially dangerous)

Classification code C2 indicates that, whilst those using the installation may not be at immediate risk, urgent remedial action is required to remove potential danger. The NICEIC contractor issuing this report will be able to provide further advice.

It is important to note that the recommendation given for the next inspection date in PART 4 of this report is conditional upon all items which have been given a Classification code C1 and code C2 being remedied immediately and as a matter of urgency, respectively.

It would not be reasonable for the inspector to indicate that the installation is in a satisfactory condition if any observation in this report has been given a code C1 or code C2 classification.

Classification code C3 (Improvement recommended)

Where an observation has been given a Classification code C3, the inspection and/or testing has revealed a noncompliance with the current safety standard which, whilst not presenting immediate or potential danger, would result in a significant safety improvement if remedied. Careful consideration should be given to the safety benefits of improving these aspects of the installation. The NICEIC contractor issuing this report will be able to provide further advice.

Code FI (Further investigation required without delay)

It should usually be possible for the inspector to attribute a Classification code to each observation without indicating a need for further investigation.

However, where 'FI' has been entered against an observation the inspector considers that further investigation of that observation is likely to reveal danger or potential danger that, due to the agreed extent or limitations of the inspection and/or testing (entered in PART 6), could not be fully identified at the time.

It would not be appropriate for the inspector to indicate that the installation is in a satisfactory condition if there is reasonable doubt as to whether danger or potential danger exists. Consequently, where the inspector has indicated 'Further investigation required without delay' (FI) the overall assessment of the installation (PART 3) should be marked as 'Unsatisfactory'.

If the inspector has indicated that an observation requires further investigation without delay, the person ordering this report is advised to arrange for the NICEIC contractor issuing the report (or another skilled person or persons competent in such work) to undertake further examination of that aspect of the installation as a matter of urgency, to determine whether or not danger or potential danger exists.

Further information

Further information on the application of Classification codes, primarily aimed at inspectors but of possible interest to persons ordering condition reports, can be found in Electrical Safety First's Best Practice Guide No 4 *Electrical installation condition reporting: Classification Codes for domestic and similar electrical installations*. The guide can be viewed or downloaded free of charge from www.electricalsafetyfirst.org.uk

For further information about electrical safety and how NICEIC can help you, visit www.niceic.com