

Landlord Gas Safety Record

Cert. No. 166

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address						Customer / Landlord							
Engineer		Deklan Simpson				Name							Name	Mr Lisa Grimbley						
Company Address		Simtec Plumbing And Heating 27				Address	2	2					Company Address							
							Ba	Barstow Avenue						rose cottage						
		Stray road					Yo	York												
		York				Back Carda								Stamford Bridge York						
			Post Code							VO41 111V										
Post Code		YO31 ONE				Tel. No	el. No Tel. No							YO41 1HX						
Tel No.		07415903753											101.100							
Gas Safe Reg		3916101																		
ID Card No.		3916101																		
۸n	oliance D	otails						Incher	tion Details											
¬μ	Location		Appliance Type	Make	Mode	el Flu	Flue Type			Operating Pressure	Heat Input (kW/h)	High Combust	on Low Combustion	Safety device(s)	Ventilation	Visual condition	Flue	Appliance	Appliance safe	
								Appliance		(mbar)		Reading	Reading	correct	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
												Ratio CO ppm	CO2 Ratio CO CO			satisfactory				
1	Kitcher	n	Boiler	Ideal	Isar He	e 24	NA	Yes	Yes	18.9	24	0.0011 163	9.2 0.0001 11 8.	B Yes	Yes	Yes	Pass	Yes	Yes	
2 Kitche		n	Hob Newworld Unkr			own	NA	Yes	Yes	NA	NA	NA NA	NA NA NA NA	A No	NA	NA	NA	NA	Yes	
3																				
4																				
5																				
6		_								Labala a										
De	efects / Identified							Labels and Warning Notice Issued					CO Alarm(s) Sr				Smoke Alarm(s)			
	1 2	NCS no fads on ho									NA			CO Alarm(s) fitted Yes			Smoke Alarm(s) fitted Yes			
	3										NA						Shicke Alami(s) fitted			
4													CO Alarm(s) tested		Pass	Smoke Alarm(s) tested		ted	Pass	
5														and Satisfactory			and Satisfactory			
	6																			
Em	ergency Co	ntrol Access	ible Yes Gas	Tightness Satisfactory Yes	5	Comn	nents													
Gas Installation Pipework Visual Inspection Satisfactory Yes																				
Equipotential Bonding Yes																				
NE	XT INSPEC	TION DUE	ON OR	03-Dec-2023																
BE	FORE																			
	natures																			
lss	ued by:	Signed	XIII.	1		Received S	igned						Date	23-N	ov-2022					
			I I C	1	L	by:														
Pri	nt Name		Deklan Simpso	n	F	Print Name														