

Serial No
PAD02/

LANDLORD/HOMEOWNER GAS SAFETY RECORD



This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

Details of Registered Business

Gas Safe Register No: 206115

Registered Engineer's Name: 8-James Harker

Gas Safe Register Licence No: 5312754

Business: N G Plumbing & Heating Ltd

Address: Willow Bank - 4 Waterside, Hemingbrough

Selby

Postcode: YO8 6RD

Contact No: 01757 630633

Details of Site

Name (Mr/Mrs/Miss/Ms):

Address: 9 Sails Dr

9 Sails Drive, York

Postcode: YO10 3LR

Contact No:

Details of Customer/Landlord

Name (Mr/Mrs/Miss/Ms): Andy Cobley

Address: Andy Cobley

2a Sycamore Terrace

York

Postcode: YO30 7DN

Contact No: +447971791271

Number of Appliances tested: Two

Appliance Details

	Location of	Type	Manufacturer	Model	Owned by Landlord/Homeowner	Inspected Yes/No	Type of flue
1	Loft	Heat only boiler	Vaillant	Ecotec plus 415	Yes	Yes	Room sealed
2	Kitchen	Hob	CDA	HG9320055	Yes	Yes	Flueless
3							
4							

Inspection Details

	Operating pressure in mbar and/or heat input kW/h or Btu/h	Operation of safety device(s)	Ventilation satisfactory	Visual Condition of flue and termination	Flue operation checks	Combustion analyser reading	Appliance Serviced	CO Alarm Fitted	CO Alarm tested (if Fitted)	SAFE TO USE
1	19.88mbop	Pass	Yes	Pass	Pass	9.4% Co2 24ppm 0.0003	Yes	Yes	Yes	Yes
2	11kw	Pass	No	N/A	N/A		No	Yes	Yes	Yes
3										
4										

Safety Related Defect(s) Identified

	GIUSP Classification	Warning/Advisory Record insert form serial No*
1		
2		
3		
4		

Remedial Action Taken

1	
2	
3	
4	

Details of Work carried out

Landlords gas safety check

Outcome of gas installation pipework visual inspection	Pass
Outcome of gas supply pipework visual inspection	Pass
Is the Emergency Control Valve access satisfactory?	Pass
Outcome of gas tightness test?	Pass
Is the protective Equipotential bonding satisfactory?	Pass

Record Issued by: J Harker

Date appliance(s)/flue(s) checked: 15/08/2022

Received by name: No one in

Received by: Tenant

Attention

Next safety check
due by:
15/08/2023