



## Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe

Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

(Integrity, Construction and Lining) has been carried out.

Nicola 80 Crossways

Certificate No: G.M.2822

Certificate Reference

Engineers Details								Installation Details						Client Details							
Trading Title		G M Plumbing And Heating							allation						Client Address	Nicola	a				
Address		3 Norseway							lress	80 Crossways					Address	24 Th	24 The Village				
		Stamford Bridge								Badger H	lill					Wiggi	nton				
		York								York						York					
		Post Code: YO41 1DR									Post Code: YO10 5JF							F	Post Cod	le: YO322	2PJ
Gas Safe No:		182126 Telep		Telepho	ohone No: 079705		555916		Telephone N		lo:		Telephone No:								
Appliance Details										Inspec	tion Deta	ails									
	Locatio	Location		Туре	Make		Model		Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (WD Vibual Inspector Only)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Venulation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)
1	Kitchen		Hob		Hotpoint		Na		null	null	19 mb	Na	YES	FL	YES	YES	YES	NA	NA	NA	YES
2	Loft		Central heatin		boiler Worcester		Greenstar 15 RI HE		0.0001	0.0012	17 mb	137	YES	RS	YES	YES	YES	YES	NA	YES	YES
3																					
4																					
5																					
Faults/Notes								Remedial Work Taken									Warnir	ng Notic	e Fixed		
1																					
2																					
3																					
4																					
5																					
Emergency Control Valve Accessible:  YES  Gas Tightness Satisfactory:  YES										Signatures  Report Issued By:  Gas ID Number:									5046510		
Gas Installation Pipework Visual Inspection Satisfactory:										Name: G Murray Signed: C Date:								Wed-23-08-2023			
Num	ber of Applia	ances Te	sted:	2	Equipo	otential E	Bonding: Y	ΈS	Re		ceived E	By:		-				_			
NEXT INSPECTION DUE ON OR BEFORE:  Sat-06-07-2024 Installation Pass: YES								me:	Signed: Date:						Wed-23	-08-2023					
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES												This Gas Sa	afetv Report w	as created b	v Gas Checker So	oftware all rights r	eserved ww	/w.gaschecker.co.	uk		