

## **Landlord Gas Safety Record**

Cert. No. 10524

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landiord							
Engineer Company Address Post Code Tel No.		Anthony Stannard Nortons Heating Suite 4a Heritage House Osbaldwick York				Name	Un	Unknown						1	Mr Paul Blac	les					
						Address	114				Compa										
							Thief Lane					Addres	S Z	4							
							Yo	York						ŀ	Hill Garth						
							North Yorkshire						١	York							
						Post Code YO10 3HU						1	North Yorkshire								
		YO19 5UW 01904411040				Tel. No	Unknown					Post Co	ode y	YO41 5BP							
							O.						Tel. No								
Gas	Safe Reg																				
ID Card No.		5424728																			
App	oliance D	etails					Inspection Details														
	Location		Appliance Type	Make	Mode	4	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combus Reading	tion Low Combustio Reading		Safety device(s) correct	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
								Арриансс		(IIIDai)		Ratio CO	CO2 Ratio	CO CO2	operation	satisfactory	termination satisfactory	test	Serviced	to use	
7	Vitala a		Deller	Mayaashay	Cunamata	- 20 - d:	D.C.	Vaa	Vaa	20.5	20	ppm		ppm %	Van	Vac		Dona	Van	Vas	
1	Kitcher		Boiler	Worcester	Greenstar		RS	Yes	Yes	20.5	30	0.0006 60				Yes	Yes	Pass	Yes	Yes	
2 Kitche		n Hob I		Indesit	Unknown		FL	Yes	Yes	20.5	5.60	NA NA	NA NA	NA NA	Yes	Yes	NA	NA	No	Yes	
3																					
4																					
5 6																					
		1.c. 1								Labole a	nd Warning No	tico Issued	O AI	( )			C I	A1 / '			
Det	ects / Ide	lentified									Labels and Warning Notice Issued			CO Alarm(s)				Smoke Alarm(s)			
	1																				
2										No		CO Ala	arm(s) fitt			Smoke Alarm(s) fitted		ed	Yes		
4													CO Alarm(s) tested Pass and Satisfactory			Smoke Alarm(s) tested and Satisfactory Pass					
5 6													and So	atistactory	У		and Sau	Stactory			
	U																				
Em	ergency Cor	ntrol Acces	ssible Yes Gas	Tightness Satisfactory Yes	3	Comn	nents														
Gas	Installation	n Pinework	Visual Inspection	Satisfactory Yes																	
		·		Satisfactory res																	
	Equipotenti	ial Bonding Yes																			
Water quality/level of inhibitor acceptable Yes																					
NEXT INSPECTION DUE ON OR 16-Nov-2024																					
	XI INSPEC FORE	HON DUE	E ON OR	10-1100-2024																	
JEI	JIL																				
Sig	natures																				
	ued by:	Signed				eceived Signed									15-N	ov-2023					
			Minn		b	y:															
				× 1																	
Prir	nt Name		Anthony Stanna	ard	Р	rint Name		Antho	ny Stannard												