



## Domestic/Landlord Gas Safety Record Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe

Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues

(Integrity, Construction and Lining) has been carried out.

Nick 30 12a Lilac Ave

Certificate No: G.M.2816

Certificate Reference

Engineers Details								Installation Details						Client Details							
Trading Title		G M Plumbing And Heating						Installation Address							Client Addres	Nick F	Read				
Address		3 Norseway							ress	12a Lilac Avenue					Addres	S   14 WI	14 Whitelands				
		Stamford Bridge								York						Earsv	Earswick Chase				
		York													York						
		Post Code: YO41 1DR								Post Code:					Post Code: Y032 9FX						
Gas Safe No:		182126 Tele		Telephone N	ephone No: 0797055		55916		Telephone N		o:			Telephone No:							
Аp	pliance De	Details									Inspection Details										
	Location		Appliance	Туре	Make		el	Combustion LOW (CO2% or CO/CO2 ratio)	Combustion HIGH (CO2% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Bedroom Co	upboard	Combi b	oiler	Vokera		3 HE	Na	0.0022	20 mb	194	YES	RS	YES	YES	YES	YES	NA	YES	YES	
2																					
3																					
4																					
5																					
Faults/Notes							Remedial Work Taken								Warning Notice Fixed						
1																					
2	2																				
3	3																				
4																					
5																					
Emergency Control Valve Accessible:  YES  Gas Tightness Satisfactory:  YES									Signatures Report Issued By: Gas ID Number:									504651	0		
Gas	Installation F	Pipework	Visual Inspe	ection Satisfac	ory:	[		Name: G Murray Signed: C Date:							Fri-11-08-2023						
Num	ber of Appli	ances Te	sted:	1 Ec	uipotent	tial Bonding:	YES		Report Received By:												
NEXT INSPECTION DUE ON OR BEFORE:  Sun-11-08-2024 Installation Pass: YES							ıme:	Signed: Date:						Fri-11-08-2023							
CO Alarm fitted & working? YES Smoke alarm fitted & working? YES											This Gas Sa	afetv Report w	as created b	v Gas Checker S	oftware all rights	reserved ww	vw.gaschecker.co	.uk			