

## Landlord Gas Safety Record

Cert. No. 997

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord								
Engineer		Stephen Kelly				Name							Name		Mr Nick Alliott						
		STK Plumbing & Heating				Address	33	31					Company		The Property Company						
Address		Haxby York North Yorkshire					м	Markham Street					Address		23						
							Yo	York							Front Street						
															Acomb, York						
		North Yorkshire				Post Code	5														
Post Code		YO32				Tel. No							Post Code								
Tel No.		07784527160											Tel. No	C							
Gas Safe Reg																					
ID Card No.		4043404																			
		_																			
Ар	oliance D	etails						Inspec	ction Details												
Location		n Appliance Type		Make	Mode	el Flue	Flue Type	Landlord's Appliance	lord's Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combus Reading	tion Lo	w Combustior Reading	on Safety device(s correct	) Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
								Appliance		(mbar)		Ratio CO	CO2 Rati	o CO CO	2 operation	satisfactory	termination satisfactory	test	Sciviccu	touse	
1	Quthuild	1	Deiler	Ideal	Europa	220	DC	Vee	Vee	10.0	20		%	ppm %		Vaa		Deee	Vaa	Vaa	
1	Outbuildi	ing	Boiler	Ideal	Europa	228	RS	Yes	Yes	19.8	28	0.0004 14	6.7 NA		A Yes	Yes	Yes	Pass	Yes	Yes	
2 3																					
4																					
5																					
6																					
_	e									Labols a	and Warning No	atica Issued		1			Currelia	Al	•		
Dei	fects / lde	ientified				Labels and Warning Notice Issued					CO Alarm(s)				Smoke Alarm(s)						
	1										NA										
	2												CO A	arm(s) fi	ted	Yes	Smoke	Alarm(s) fitt	ed	Yes	
	3																				
	4 5													arm(s) te atisfacto		Pass		Alarm(s) tes isfactory	sted	NA	
	6												and 3		i y			islactory			
	-																				
Em	ergency Co	ntrol Ac	ccessible Yes Gas	Tightness Satisfactory Ye	s	Comr	ments														
Ga	s Installatior	n Pipew	ork Visual Inspection	Satisfactory Yes		Serv	viced gas	boiler , <b>f</b>	No earth bond fo	ound at gas me	eter										
				,																	
Equipotential Bonding No																					
NEXT INSPECTION DUE ON OR 05-Mar-2022																					
BE	FORE																				
	natures																				
lss	ued by:						Received Signed							Date 10-Feb-2021							
			$\supset 1/2$	Celly	k	by:															
					_					_											
Prii	nt Name		Stephen Kelly		F	Print Name															