

Landlord Gas Safety Record

Cert. No. 420

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer						Job Address							Customer / Landlord								
Engineer Deklan Simpson					Name Address								ame	(Corrina						
Company						4	4						ompany	1	MBE Limited						
Address	27					Penyghent Avenue							ddress		villa farm wigginton road York						
	Stray road					Yo	York														
	York														York						
					Post Code																
Post Code YO31 0NE				Tel. No	1032 2101																
Tel No. 01904412109				Tel. No								el. No	1								
Gas Safe Reg 3916101																					
ID Card No. 3916101																					
Appliance Details																					
Appliance Details Location Appliance Type Make Model						Flue Type	Inspection Details Type Landlord's Appliance Inspected Operating Pressure Heat Input (kW/h) High C					mbustion	Low Com	hustion	Safety device(s)	Ventilation	Visual condition	ual condition Flue		Appliance safe	
Location		Appliance Type	Make	Mode		riue Type	Appliance	Appliance inspected	(mbar)	rieat input (kw/ii)	Read	ding	Read Ratio	ding	correct	Provision satisfactory	of flue and termination satisfactory	Performance test	Appliance Serviced	to use	
1 Bedroo	m	Boiler	Ideal	Logic Max	30kw	NA	Yes	No	19.1	30			0.0001		Yes	Yes	Yes	Pass	NA	Yes	
2 Kitche	n			XTG65			Yes	Yes	NA	NA			NA	-	-	Yes	NA	NA	NA	Yes	
3																					
4																					
5																					
6																					
Defects / Identified Labels and Warning Notice Is												otice Issue	d CO A	larm(s)							
1														NA							
2														NA			CO Ala	arm(s) fitted	l	Yes	
3																					
	4 5																CO Alarm(s) tested and Satisfactory Pass				
6																	anu S	atisiactory			
,																					
Emorgonsy Co	ntral Ac	cossible Vos	T' 1		Comn	nents															
Emergency Co	DILITOT AC	cessible Yes Gas	Tightness Satisfactory Yes		COITIII	ICIICS															
Gas Installatio	n Pipewo	ork Visual Inspection	Satisfactory Yes																		
Equipotent	tial Bond	lina Yes																			
			20.0-+ 2025																		
NEXT INSPEC	CTION D	UE BEFORE	30-Oct-2025																		
Signatures																					
Issued by:	Signed				eceived Signed								Date		30-O	ct-2024					
					y:	•															
Print Name		Deklan Simpsor		Р	rint Name																
		2 3a 3ip301																			