

Domestic/Landlord Gas Safety Record

Safety inspection and reporting carried out in accordance with Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure. Unless stated otherwise, no detailed internal inspection of flues (Integrity, Construction and Lining) has been carried out.

Certificate Reference

Nicola 2 80 Crossways

Certificate No: G.M.2907

Engineers Details						Insta	Installation Details						Client E						
Trading Title		G M Plumbing And Heating					Installation						Client	Nicol	а				
Address		3 Norseway					dress	80 Crossways				Addres	⁵⁵ 24 TI	24 The Village					
		Stamford Bridge					Badger Hill					Wigginton							
		York						York						York					
		Post Code: Y041 1DR						Post Code: YO10 5JF					Post Code: Y				de: YO32	2PJ	
Gas Safe No:		182126 Telephone No: 07970555916				 	lephone N	lo:					Telephone No:						
Appliance Details						·		Inspec	ction Det	ails				L]			
	Location		Appliance Type	Make	Model	Combustion LOW (C02% or CO/CO2 ratio)	Combustion HIGH (C02% or CO/CO2 ratio)	Heat Input (KW) or Operating Pressure	CO Reading (ppm)	Appliance Inspected (YES/NO/NA/VIO) (VO - Vaul Inspecto ON)	FlueType (OF/RS/FL)	Landlords Appliance (YES/NO/NA)	Safety Device(s) Correct Operation (YES/NO/NA)	Ventilation Provision Satisfactory (YES/NO)	Visual Condition Of Flue and Termination Satisfactory (YES/NO/NA)	Flue Performance Test (PASS/FAIL/NA)	Appliance Serviced (YES/NO/NA)	Appliance Safe To Use (YES/NO)	
1	Kitche	en	Hob	Hotpoint	Na	null	null	19 mb	Na	YES	FL	YES	YES	YES	NA	NA	NA	YES	
2	Loft		Central heating boi	ler Worcester	Greenstar 15 RI HE	0.0003	0.0018	17 mb	196	YES	RS	YES	YES	YES	YES	NA	YES	YES	
3																			
4																			
5																			
Faults/Notes							Remedial Work Taken									Warning Notice Fixed			
1																			
2																			
3																			
4																			
5																			
	I ergency Cont essible:	trol Valve	YES		Signatures Gas ID Number:										5675325				
		Pipeworł	k Visual Inspection		Report Issued By: Name: G Murray Signed: Comparison Date:														
	nber of Appli			Equipotential	Bonding: YES	٦									Mon-29-07-2024				
NEXT INSPECTION DUE ON Sun-06-07-2025 Installation Pass: YES							eport Re ame: 「	Received By: Signed: Date:							Mon-20	Mon-29-07-2024			
						יי ן ר													
CO	CO Alarm fitted & working? YES Smoke alarm fitted & working? YES							This Gas Safety Report was created by Gas Checker Software all rights reserved www.gaschecker.co.uk											

For appliances not owned by the Landlord the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.