

Landlord Gas Safety Record

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Co	mpany / I	nstaller				Job Addre	ess						Custome	er / L	andlord						
Engineer		Kenny Oxtoby				Name	The Occupier						Name								
Company Address Post Code		York Heating Services Ltd				Address						Company		PDA Estates							
							Os	Osbaldwick Lane					Address		7						
		Forest Way					Yo	York							Cheviot Court						
		York													Garforth						
		North Yorkshire				Post Code	YC	YO10 3BL							Leeds						
		YO31 1BJ				Tel. No							Post Cod		LS25 2JU						
Tel No.		07878111999											Tel. No		019042132	14					
Gas Safe Reg		660648																			
ID Card No.		5646156																			
٩Þ	pliance D	etails						Inspec	ction Details												
Locatio				Make	Mode	al Flu	Flue Type	Landlord's Appliance Inspected		Operating Pressure	Heat Input (kW/h)	High Combust			n Safety device(s)	Ventilation	Visual condition		Appliance	Appliance safe	
								Appliance		(mbar)		Reading Ratio CO	CO2 Ratio C	ding	correct	Provision satisfactory	of flue and termination	Performance test	Serviced	to use	
												ppm	% p	om %	-		satisfactory				
1	Kitcher	n Co	ombination Boiler	Worcester	24 Cdi	RSF	FF	Yes	Yes	13.2	NA	0.0002 14	7.5 —— -	- -	- Yes	Yes	Yes	Pass	Yes	Yes	
2																					
3																					
4																					
5																					
6	<u> </u>									Labola a	nd Warning No	tico locuod		()							
Je	efects / Ide	lentified				Labels and Warning Notice Issued				Juce Issueu	CO Alarm(s)			Option	Optional Checks						
	1								NA			CO Alarm(s) fit		tted Yes		Smoke Alarm(s) fitted		Yes			
	2												00.41								
	3												CO Alarm and Satis			Pass		Alarm(s) tes isfactory	sted	Pass	
	4 5														. ,			,			
	6																	uality/level	of inhibito	r NA	
																	accepta	ble			
Εm		ntrol Acce	ssible Yes	Tightness Satisfactory Yes	_	Comm	ents														
					5		ento														
Ga	is Installation	n Pipework	k Visual Inspection	Satisfactory Yes																	
Equipotential Bonding Yes																					
NE	EXT INSPEC		E BEFORE	06-Nov-2025																	
	gnatures																				
lss	sued by:	Signed	11 Bench			Received Si	gned						Date		06-N	ov-2024					
			K, Altor		Ľ	by:															
Pri	int Name		Kenny Oxtoby		F	Print Name		D. Co	olican												