Landlord Home Owner Gas Safety Record

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and the lining has NOT been carried out.



Gas safe ID 561126 1 PlumbCORE Y Workshop 3 N					Job address 19 Owston Avenue York North Yorkshire YO103AH			Mr Edw Homest Shaw Li Oxenhoc Keighle West Yo BD2290 +44 07	ane pe y prkshire QL 920055299		Certificate information Date 08/11/2024 Number 1510 Next inspection due 08/11/2025		
No	Location	Appliance type Make/		Make/me	model		Flue type	Landlords appliance	Appliance insp?	Combustion analyser reading	Operating pressu or heat input	Ire Safety device correct opera	e(s) ation
1	Kitchen	itchen Combination boiler		Worcester Bosch/Greenst		nstar 4000	RS	Yes	Yes	9.8	19.8mbar	Yes	
No	Ventilation provision Visual condition of t satisfactory termination satisfac		lition of th 1 satisfact	the flue & Flue performance checks		Appliance serviced		Appliance safe to use	Approved CO alarm fitted?	Is CO alarm in date?	Testing of CO ala satisfactory	arm	
1	Yes		Yes		Pass		Yes		Yes	Yes	Yes	Yes	
		_			_			10/	unio un (Biologia a	Nuclear Court			1
No	o Defect(s) identified Re				Remedial act	emedial action taken			ning/Advice ce issued	Number of appliances tested 1 Gas installation pipework (visual inspection) satisfactory? Ye			
										Gas tightness test satisfactory?			Yes Yes
										Emergency control valve accessib			Yes
										Protective equipotential bonding satisfactory?			Yes
													Yes
Engi	neer information				Received by information Comments								
Gas	neer name: Steve Pla safe card ID: 560900 ature:				Name: Received by: No person present Signature:								