

Print Name

Paul Richardson

Print Name

P. Richardson

Landlord Gas Safety Record

Cert. No. 12026

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							ob Address							Customer / Landlord							
En	gineer	Paul Richardson					U	Unknown													
Со	mpany	Nortons Heating Suite 4a Heritage House				Address	11	14						Paul Blades							
Ad	dress						Thief Lane					Address	4								
Post Code		Osbaldwick						York					Hill Garth								
		York												York							
		IVIK				Post Code YO10 3HU															
		YO19 5UW				Tel. No		nknown					Post Code	YO41 5BP							
Tel No.		01904411040											Tel. No								
Gas Safe Reg																					
ID Card No.		5424730																			
		J4247	730																		
Ар	pliance D	etails						Inspec	tion Details												
	Location		Appliance Type	Make	Mode	ıl F	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)) High Combustion Reading	ion Low Combustion Reading	Safety device(s) correct	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use		
								"					CO2 Ratio CO C	operation	satisfactory	termination satisfactory	test				
1	Kitcher	n	Boiler	Worcester	Greensta Combinatio		RS	Yes	Yes	18	30	0.0005 47 9	9.4 0.0000 2 8	.5 Yes	Yes	Yes	Pass	Yes	Yes		
2 Kitche		n	Gas Hob	CDA	Not Fo	und	FL	Yes	Yes	20	5.6	NA NA	NA NA NA N	A Yes	Yes	NA	NA	NA	Yes		
3																					
4																					
5																					
6																					
De	fects / lde	entifie	ed				Labels and Warning Notice Issued					CO Alarm(s)			Option	Optional Checks					
1										No			CO Alarm(s) fitted Yes			Smoke A	Smoke Alarm(s) fitted Yes				
2											No										
3													CO Alarm(s) tested Pass				Smoke Alarm(s) tested				
4													and Satisfacto	ory	. 455	and Sat	isfactory				
5																Water	uality/lovel	of inhihito			
	6														Water quality/level of inhibitor Yes						
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																					
Gas Installation Pipework Visual Inspection Satisfactory Yes Smoke alarms are mains HMO tested by a third party.																					
Equipotential Bonding Yes																					
NEXT INSPECTION DUE BEFORE 16-Nov-2025																					
HEAT HIGH ECTION DOL DEL ONE																					
Sic	natures																				
	ued by:	Signe	ed	→	F	Received S	Signed		1/2				Date	13-N	ov-2024						
		_	eu																		