

Landlord Gas Safety Record

Cert. No. 136

York Heating Services Ltd

Kenny Oxtoby

Print Name

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / Installer							Job Address							Customer / Landlord								
Engineer		Kenny Oxtoby				Name	Th	The Occupier								Mr Darren Coolican						
Company Address Post Code Tel No.		York Heating Services Ltd				Address								Company								
							Ma	Manor Court					A	ddress		7						
		Forest Way					Yo	York								Cheviot Court						
		York														Garforth						
		North Yorkshire				Post Code	YC	10 3EU								Leeds						
		YO31 1BJ				Tel. No							P	ost Code	<u> </u>	LS25 2JU						
		07878111999											T	el. No								
Gas Safe Reg																						
ID Card No.		5646156																				
Apr	oliance D	etails					Inspec	ction Details	5													
Locatio				Make	Mode	el f	Flue Type	Landlord's Appliance Insp		_	Heat Input (kW/h)	High Combu Reading	bustion	tion Low Comb		tion Safety device((s) Ventilation	Visual condition	Flue	Appliance Serviced	Appliance safe	
								Appliance		(mbar)			ing CO CO			correct operation	Provision satisfactor	of flue and termination	Performance test	Serviceu	to use	
												p	pm %	р	pm %			satisfactory	_			
1	Bedroor Cupboar		Combination Boiler	Worcester	28i Jui	nior	FF	Yes	Yes	13.7	NA	0.0005	32 6.	4 -	- -	- Yes	Yes	Yes	Pass	Yes	Yes	
2																						
3																						
4																						
5																						
6																						
Defects / Identified							Labels and Warning Notice Issued						d	CO Alarm(s)				Option	Optional Checks			
1								NA				- II.	CO Alarm(s) fitted			Yes	Yes Smoke Alarm(s)		ted	Yes		
2								IVA														
3													CO Alarm(s) tested				Smoke Alarm(s) tested					
4													_ '	and Satis	stacto	ry		and Sat	isfactory			
5												-11					Water	uality/leve	of inhibito	r		
	б																accepta		OI IIIIIIDICO	r NA		
Emergency Control Accessible Yes Gas Tightness Satisfactory Yes Comments																						
Gas Installation Pipework Visual Inspection Satisfactory Yes																						
	Equipotenti	ial Bond	ling Yes																			
NF	XT INSPEC	TION D	UE BEFORE	18-Oct-2025																		
	X1 11131 EC		OL BLI OIL																			
	natures																					
	ied by:	-				Received S	Signed	OP 1.						Date 18-Oct-2024								
			K, Males		b	by:																

D. Coolican

Print Name