Job Reference: 5026059



Landlord Gas Safety Record

This inspection is for gas safety purposes only to comply with the Gas Safety (Installation and Use) Regulations. Flues have been inspected visually and checked for satisfactory evacuation for products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

For Appliances not owned by a landlord, the recorded 'Appliance Safe' response is based on a visual check for obvious defects only.

Nunthorpe Services

10 Rawcliffe Drive York YO30 6PE **Tel**: 07921908320

Web: www.nunthorpeservices.co.uk

Registration No.: 209036

Inspection / Installation Address	Landlord / Agent Address				
The Occupier	Kevin Blades				
87 Danum Road, York, North Yorkshire, YO10 4HY	Stoneleigh, Sandhill Lane, Sutton On Derwent, York, North Yorkshire, YO41				
	4BX				

	Appliance Detail						Flue	Flue Tests Inspection Details									
Location					264 2 4 4 4			Combustio	Combustion Analysis		EL 10 L					Safe	
	Location	n Description	Type	e Flue Type	e Operating Pressure / KW Input	Safety Device(s) Correct Operation	Test	Test	High	Low	Termination	Flue Visual Condition	Adequate Ventilation	Landlord's Appliance	Inspected Se	Serviced	d to
									CO:CO2 CO CO2	CO:CO2 CO CO2							use
1	Kitchen	worcester, cdi	Combi boiler	Room Sealed	19.2Mbar	Yes	n/a	n/a	0.0011 112 9.7%	0.0001 11 9%	Yes	Pass	Yes	Yes	Yes	Yes	Yes

	Faults	Remedy	Warning Notice Issued	Warning Tag or Sticker Fixed
1		-	No	No

Engineer Notes

	Gas Install	ation Pipework	Smoke / Heat Detector Test				
Satisfactory Visual Inspection	Yes	Emergency Control Accessible	Yes				
Satisfactory Gas Tightness Test	Yes	Equipotential Bonding Satisfactory	Yes				
Pipework Warning Notice Issued	No						

-	- '				
	NEXT GAS	SAFETY CHECK MUST BE CARRIED OUT	T BY 20/01/2026		
	Received on behalf of the landlord			Engineer's Signature	
Name	Customer's signature unavailable	I certify that I carri∈	ed out the inspection on the ap	pliances detailed above	
		Name	Mr Alan Tennent		0
		Card ID	4470717		
		Inspection Date	20 January 2025		säfe

sate