

## **Landlord Gas Safety Record**

Cert. No. 1158

Safe
W.Duggan Plumbing & Heating

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations and the Gas Industry Unsafe Situations Procedure.

Company / I	Job Address						Customer / L	andlord									
Engineer	Wayne Duggan			Name						Name							
Company	W.Duggan Plumbing & Heating			Address	Basement flat 23					Company	Executors of D.Leeper deceased						
Address					Park Str	eet				Address	12						
	York Road				York						Station Road						
	North Duffield, Selby				York						Upper Poppleton						
	North Yorkshire			Post Code	YO24 1BQ						York						
Post Code				Tel. No		•					YO26 6PY						
					Tel. No												
	0.7.1000.1202																
	Gas Safe Reg 22202																
ID Card No.	5287064																
Appliance Details Inspection Details																	
Location	Appliance Type	Make	Mode	el Flue	Type Landlo	d's Appliance Inspecte	d Operating Pressure (mbar)	Heat Input (kW/h)	High Combusti Reading	on Low Combustion Reading	Safety device(s) correct	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
					Арриа		(mbar)		Ratio CO	CO2 Ratio CO CO	operation	satisfactory	termination satisfactory	test	Scrviccu	to use	
1 Kitchen Cup	board Boiler	Ideal	Logic -	1 20	S Ye	Yes	17.81	30	ppm	% ppm % 9.2 0.0004 35 8.9		Yes		Page	Yes	Yes	
	Dodru Bollei	lueal	Logic -	F 30   F	.5 Te	i les	17.01	30	0.0011 101	9.2 0.0004 35 6.	9 Yes	res	Yes	Pass	res	res	
2       3																	
5	4																
6 Labels and Warning Notice Issued CO Alarm(s)																	
Defects / Ide	entified				Labeis an	a warning N	otice issue	CO A	arm(s)								
1										NA							
2													CO Ala	arm(s) fitted	t	Yes	
3													-				
5														arm(s) teste atisfactory	ea .	Pass	
6													una s	acioiaccoi y			
Emergency Co	ntrol Accessible Yes Gas	Tightness Satisfactory Vo	c	Commer	nts												
s , and ingritiness substitution, res																	
Gas Installation	n Pipework Visual Inspection	Satisfactory Yes															
Equipotenti	al Bonding Yes																
NEXT INSPEC	TION DUE BEFORE	04-Nov-2025															
Signatures																	
Issued by:	Signed	M		Received Signe	ed					Date	04-N	ov-2024					
		U	t	y:													
Print Name Wayne Duggan Print Name																	