

## Landlord/homeowner Gas Safety Record

This inspection is for gas safety purposes only to comply with Gas Safety (Installation and Use) Regulations. Flues have been inspected and checked for satisfactory evacuation of products of combustion. A detailed internal inspection of the flue integrity, construction and lining has NOT been carried out.

| Company details                    | Job address      | Landlord/Agent                     | Certificate information                |  |
|------------------------------------|------------------|------------------------------------|--|--|
| M Collins Plumbing and Heating LTD | 8 Nevinson Grove | Anwar                              | Date: 21/02/2025                       |  |
| 35 Crossfield Crescent             | York             | Two oaks 15 wenlock drive Escrick. | Certificate number: CP12-1456          |  |
| York                               | England          | YO19 6JB                           | Certificate is valid until: 21/02/2026 |  |
| YO19 4QJ                           | YO10 4HR         |                                    |  |  |
| 07513468391                        |                  |                                    |  |  |
| Gas safe id: 924253                |                  |                                    |  |  |

| No | Location | Appliance<br>type | Make/model             | Flue type | Landlords<br>appliance |     |        | Operating<br>pressure<br>(mbar) | heat<br>input<br>(kW) | Safety device(s) correct and operational |
|----|----------|-------------------|------------------------|-----------|------------------------|-----|--------|---------------------------------|-----------------------|--|
| 1  | Kitchen  | Boiler            | Ideal Logic + combi 35 | RS        | Yes                    | Yes | 0.0013 | 17.5                            | 34.12                 | Yes                                      |
| 2  |          |                   |                        |           |                        |     |        |                                 |                       |  |
| 3  |          |                   |                        |           |                        |     |        |                                 |                       |  |
| 4  |          |                   |                        |           |                        |     |        |                                 |                       |  |

| No |     | Visual condition of flue & termination satisfactory |      | Appliance<br>serviced? | Appliance safe to use? | Approved Co alarm fitted? | Is Co alarm in<br>date? | Testing of Co<br>alarm<br>satisfactory? |
|----|-----|---|------|------------------------|------------------------|---------------------------|-------------------------|---|
| 1  | Yes | Yes   | Pass | Yes                    | Yes                    | Yes                       | Yes                     | Yes                                     |
| 2  |     |   |      |                        |                        |                           |                         |   |
| 3  |     |   |      |                        |                        |                           |                         |   |
| 4  |     |   |      |                        |                        |                           |                         |   |

| No | Defect(s) identified | Remedial action taken | Warning notice issued? | Number of appliances tested?                                | 1   |
|----|----------------------|-----------------------|------------------------|---|-----|
| 1  |                      |                       |                        | Gas installation pipework (visual inspection) satisfactory? | Yes |
| 2  |                      |                       |                        | Gas tightness test satisfactory?                            | Yes |
| 3  |                      |                       |                        | Emergency control valve accessible?                         | Yes |
| 4  |                      |                       |                        | Protective equipotential bonding satisfactory?              | Yes |

| Engineer information           | Received by information | Comments |  |  |
|--------------------------------|-------------------------|----------|--|--|
| Engineer name: Matthew Collins | Position: Landlord      |          |  |  |
| Gas safe licence number:       | Received by: Anwar      |          |  |  |
| 1. aug                         | Anna Kar                |          |  |  |

| No |      | Working appliance<br>pressure/burner pressure (mbar) |     | Co2% | o2%  |        | Gross flue<br>temperature (°c) | Gas rate (kW) |
|----|------|--|-----|------|------|--------|--------------------------------|---------------|
| 1  | 18.5 | 17.5   | 121 | 9.5  | 20.9 | 0.0013 | N/A                            | 34.12         |
| 2  |      |  |     |      |      |        |                                |               |
| 3  |      |  |     |      |      |        |                                |               |
| 4  |      |  |     |      |      |        |                                |               |







