LANDLORD/HOMEOWNER GAS SAFETY RECORD



This record can be used to document the outcomes of the checks and tests required by The Gas Safety (Installation and Use) Regulations. Some of the outcomes are as a result of visual inspection only and are recorded where appropriate. Unless specifically recorded no detailed inspection of the flue lining, construction or integrity has been performed. Registered Business/engineer details can be checked at www.gassaferegister.co.uk or by calling 0800 408 5500

Bu	SII1622/6	rigineer details can be	e checked at www.gassa	aleregister.co.uk	of by calling 0000 2	+06 5500					MEGIOTEI
Details of Registered Business	Appliance Details										
Gas Safe Register No: 206115		Location of	Туре	Manufacturer			Model		Owned by Landlord/Homeowner		ted Type of flu
Registered Engineer's Name: 2-Paul Warriner	1	Kitchen	Boiler	W	/orcester	Gre	enstar 30i		Yes	Yes	-
Sas Safe Register Licence No:	2	Kitchen	Hob	H	Hotpoint		Nil		Yes	Yes	Flueless
susiness: N G Plumbing & Heating Ltd	3										
ddress: 1 Lavender Way, Easingwold	4										
'ork	Inspection Details										
Postcode: YO613GU Contact No: 01757 630633		Operating pressure in mbar and/or heat input kW/h or Btu/h	Operation of safety device(s)	Ventilation satisfactory	Visual Condition of flue and termination	Flue operation checks	Combustion analyser reading	Appliance Serviced	CO Alarm Fitted	CO Alarm tested (if Fitted)	SAFE TO USE
oniaci No. 01757 630633	1	17.03	Pass	Yes	Pass	Pass		Yes	Yes	Yes	Yes
etails of Site	2	19.09	Pass	Yes	N/A	N/A		No	Yes	Yes	Yes
lame:	3										
ddress: 245 Fifth Ave	4					<u> </u>					
245 Fifth Avenue York	Safety Related Defect(s) Identified								GIUSP Classification Warning/Advisory Record insert form serial No*		
YO31 0PW	1										
	2										
	4										
etails of Customer/Landlord	Pon	nedial Action T	akon								
lame: Sally Dixon	1	lediai Action 1	aken								
ddress: Sally Dixon	2										
Hawthorne Mews	3			-			-				
strensall	4										
Postcode: YO32 5RR	Details of Work carried out										
Contact No: +447793927099	Service and gas safety										
lumber of Appliances tested: 1											

Outcome of gas installation pipework visual inspection
Pass
Outcome of gas supply pipework visual inspection
Pass
Is the Emergency Control Valve access satisfactory?
Pass
Outcome of gas tightness test?
Pass
Is the protective Equipotential bonding satisfactory?
Pass

Record Issued by: p warriner

Received by name: sally

I

Date appliance(s)/flue(s) checked: 16/10/2025 Received by: Landlord

Attention

Next safety check due by: 16/10/2026