

Landlord Gas Safety Record

Cert. No. 1272

W.Duggan Plumbing & Heating

Safety Inspection and reporting carried out in accordance with the Gas Safety (Installation and Use) Regulations 1998 section 26(9) and the Gas Industry Unsafe Situations Procedure.

Company / Installer				Job Address							Customer / Landlord								
Engineer	neer Wayne Duggan			Name						Name									
Company	any W.Duggan Plumbing & Heating			Address	PSS Flat 1 23						Company		Executors of D.Leeper deceased						
Address	Park View		Pa	Park Street York					Address		12								
	York Road										Yo	Station Road							
	North Duffield, Selby				York							Upper Poppleton							
	North Yorkshire	Post Code	Y	YO24 1BQ							York								
Post Code YO8 5RU				Tel. No								de	YO26 6PY						
Tel No. 07740804161 Gas Safe Reg 22202																			
ID Card No.	5287064																		
Appliance D	etai l s					Inspec	ction Detai l s	5											
Location	Appliance Type	Make	Mod	lel	Flue Type	Landlord's Appliance	Appliance Inspected	Operating Pressure (mbar)	Heat Input (kW/h)	High Combustion	n Low Combustion Reading		Safety device(s)	Ventilation Provision	Visual condition of flue and	Flue Performance	Appliance Serviced	Appliance safe to use	
						, ippliance				Ratio CO	CO2 Ratio	co co:	operation	satisfactory		test	Scrricca	10 050	
1 Dath was	m. Dellen	lata at	La sila Ca	h : 20	D.C.	V	V	10.50	20	ppm	_	ppm %		V		NI A	V	V	
1 Bathroo Cupboa		ldeal	Logic Co	mbi 30	RS	Yes	Yes	19.50	30	0.0010 81	9.0 0.000:	5 36 8.4	2 Yes	Yes	Yes	NA	Yes	Yes	
2																			
3																			
4																			
5																			
6																			
Defects / Ide	entified										La	abels an	d Warning N	lotice Issue	ed CO A	arm(s)			
Defects / lue	entinea														CO AI	arrii(S)			
1												NA							
2															CO Ala	CO Alarm(s) fitted Yes			
3																			
	5															Alarm(s) tested Pass Satisfactory			
6															and 30	atisiactory			
Emergency Co	ntrol Accessible Yes Gas	Tightness Satisfactory Ye	S	Comn	nents														
Gas Installation	n Pipework Visual Inspection	Satisfactory Yes																	
		,																	
Equipotent	ial Bonding Yes																		
NEXT INSPEC	TION DUE BEFORE	05-Nov-2026																	
Signatures																			
Issued by:	Signed	loa		Received S	igned						Date	9	27-0	ct-2025					
	Signed	O F	I	by:															
Print Name	Wayne Duggai	ı	I	Print Name															